

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF769P

AAD2203-

Not Authorised
61 Sing & 5650h

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

04 APR 2022**SHF769P**

VF1ABL15AUC283238

200303878K

RENAULT

LATITUDE

01/04/2022

SMX3417G/CHINA

30/06/2016

PART	LIST
1 BUMPER COVER REAR	\$ <i>B₂</i> 561.70 ✓
1 BUMPER LOWER REAR	\$ <i>B₂</i> 411.90 ✓
1 BUMPER REFLECTOR LH	\$ <i>P₂</i> 16.60 X
1 BUMPER BRACKET CTR REAR	\$ <i>D₁S</i> 98.10 ✓
1 BUMPER BRACKET SIDE RH REAR	\$ <i>S₂</i> 82.10 X
1 BUMPER RETAINER RH REAR	\$ <i>S₂</i> 59.80 X
1 FENDER PANEL REAR LH	\$ <i>R</i> 1,933.20 X
1 WHEELARCH REAR LH	\$ <i>S₂</i> 275.40 X
1 BUMPER BEAM REAR	\$ <i>B₂</i> 547.80 ✓
1 BUMPER BEAM BRACKET LH REAR	\$ <i>B₂</i> 114.50 ✓
1 BUMPER BEAM BRACKET RH REAR	\$ <i>B₁</i> 114.50 ✓
1 OUTER PANEL REAR (End Panel)	\$ <i>B₂</i> 745.80 ✓
1 OUTER PANEL REAR (End Panel)TRIM	\$ <i>D₁</i> 404.56 ✓
1 BOOT REFLECTOR LAMP LH	\$ <i>CM₁</i> 277.70 ✓
1 BOOT REFLECTOR LAMP RH	\$ <i>CM₂</i> 277.70 ✓
1 TAILLAMP LH	\$ <i>CM₁CM₂</i> 401.40 ✓
1 TAILLAMP RH	\$ <i>CM₂</i> 401.40 ✓
1 BOOT REAR	\$ <i>B₁</i> 1,677.20 ✓
1 BOOT HINGE LH	\$ <i>R</i> 254.20 X
1 BOOT HINGE RH	\$ <i>R</i> 254.20 X
1 BOOT REFLECTOR LAMP LH	\$ <i>Repair</i> 277.70 X
1 TAILLAMP RH	\$ <i>S</i> 401.40 X
1 TAILLAMP LH	\$ <i>S</i> 401.40 X
	\$ 9,990.26
10%	\$ 1,594.73
	\$ 14,352.53

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF769P**AAD2203-****Special Nett**

1SET PARKING AID	\$	700.00	X
1SET REAR BUMPER CLIP	\$	66.00	✓
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	20.00	X
1SET BUMPER LOWER REAR CLIP	\$	66.00	✓
1 EXHAUST MOUNTING REAR	\$	17.82	X
2 WINDSCREEN SEALANT	\$	150.00	X
1 WINDSCREEN MOULDING	\$	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	130.00	X
TOTAL	\$	1,509.82	
TOTAL PARTS	\$	15,862.35	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	X
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	660/
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	600/
To Rust-Proofing Of The Affected Areas.	\$	170.00	60/
To reinstall rear bumper parking sensor.	\$	170.00	60/
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60/
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF769P

AAD2203-

To transfer of rear end panel fittings, attachment and
perform water seepage test. \$ 170.00 *601*

To transfer of rear windscreen fittings and conduct
water seepage test. \$ *nn* 170.00 *X*

To check steering geometry and computer wheel
alignment \$ *nn* 220.00 *X*

To Check Electrical Lighting Concerned. \$ 170.00 *201*

TOTAL \$ 7,880.00

Over All Total \$ 38,094.89

(LUMP SUM)

Repair Days

20 DAYS

5 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: