



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Customer Details				
THIRD PARTY CLAIM <i>LKK</i>			Account No.	Mr Gabriel Mark David Fenner			
			S1000020 / TPCLAIM	14 Marine Terrace			
			Document No.	#20-180			
			0	Singapore 440014			
			Document Date	Mobile: 83390475			
			04/04/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	NSP151R	AEXRKT E2	31/03/2021	SMY9414U	0	14337	65DS/SMY9414U
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MR2B23F360122289	2NR5505498	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY-AI SUNDRIES T/P INS. : CHINA TAIPING INS. T/P VEH. : PC2274H ACC DATE : 01.04.22 BY :				30	50.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)					100.00
3	B	BP-LAB2 CHK WIRING SYSTEM AND CONDUCT WATER TEST.					180.00
4	S	BP-SUBLET RESET AND REPROGRAMME ECU.					180.00
5	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.					180.00
6	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO ASSIST REPAIR. <i>(photo)</i>					360.00
7	B	BP-LAB2 REMOVE AND REINSTALL REAR W/SCREEN GLASS TO ASSIST REPAIR.					450.00
8	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, R/R FENDER AND AFFECTED PORTION OF CAR. <i>720 x 4</i>				2880	3600.00
9	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR. <i>2.5 x 500</i>				1475	2360.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts		Less
					Labour		
					Sublet		Amount Due
					Lubrication/Fluid		
					Others		

Customer Copy

Inchcape
 Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Gabriel Mark David Fenner 14 Marine Terrace #20-180 Singapore 440014 Mobile: 83390475
	Document No. 0	
	Document Date 04/04/2022	

Year	Model	Variants	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	NSP151R	AEXRKT E2	31/03/2021	SMY9414U	0	14337	65DS/SMY9414U
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MR2B23F3601222289	2NR5505498	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	1	S52159-0U963 COVER, RR BUMPER L/C <i>/ CRU</i>	1.00	557.70		557.70 ✓
11	2	S75895-0D310 TAPE, MOULDING, NO.1 <i>* X MC X NN</i>	2.00	47.30		94.60
12	3	S52575-0D340 RETAINER, RR BUMPER <i>? X NN</i>	1.00	164.30		164.30
13	4	S61601-0D260 PANEL SUB-ASSY, QUAR <i>00</i>	1.00	963.70		963.70 ✓
14	5	T21000-20 SIKA 182010 SIKA TACK GO! (BLA <i>- MC</i>	2.00	108.00		216.00 ✓
15	6	T21000-22 SIKA 207. G+P ADHESIVE PRIMER <i>- MC</i>	1.00	200.00		200.00 ✓
16	7	S64813-0D420 DAM, BACK WINDOW GLA <i>- MC</i>	1.00	34.90		34.90 ✓
17	8	S64814-0D200 DAM, BACK WINDOW GLA <i>- MC</i>	1.00	17.20		17.20 ✓

Steve (LKK)
4/5/22, 10.30am
W M
8 djs
Bel M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer
 Signature: _____

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			9,708.40
		Parts 2,248.40	GST 7.00% 679.59
		Labour 7,280.00	Less 0.00
		Sublet 180.00	
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 10,387.99

Customer Copy