

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 O.D. (TP/WS/TP RES/OD RES/EVA/INV/MV)  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 DAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 8 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

N/S	O/S

Veh No: SMY 94/44 Yr Regn: 31/3/21  
 Type:  N.Car /  M.Cycle /  Bus /  Van /  Lorry /  Taxi /  Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota VIOS c.c. 1496  
 Colour: Red A/C:  Insured /  Std /  NI / NA  
 Sp. Reading: 11871 T/Radio:  Insured /  Std /  NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MR2B 23F360172289  
 Gen. Cond:  Good /  Fair /  Poor /  Burnt  
 Steering:  In order /  Jammed /  Leaked /  Burnt or \_\_\_\_\_  
 Brake:  In order /  Jammed /  Leaked /  Burnt or \_\_\_\_\_  
 Mod:  Nil /  S/Rim /  STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 185/60R15  
 R: \_\_\_\_\_  
 BS /  DUN /  EXNOVA /  GY /  FS /  LIZA /  MIC /  OHTSU /  PIR /  SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 4 mm R/Bal. 4 mm  
 L/Bal. 4 mm L/Bal. 4 mm  
 D.O.A. 1/4/22 D.O.I. 1/5/22  
 Survey held at Borneo  
 Des. of Damages:  Frt /  Rear /  O/S /  N/S /  U/C /  Rooftop or  
Rear RH  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MR-944</u>
	final figure: \$7824.50 and 8 days
	(red, \$1883.90, 19%)

Date/Time, File Pass to?  : Prel. Report  
 : Final Report  
 1) 7824.50  
 Date/Time, File Return to?  
 2) \_\_\_\_\_  
 Report Format: tp-merimen  
 Lump Sum / I.B.F. (\$ 7824.50)

Days Of Repair: 8  
 Resurvey No. of Trip: 1  
 Add Fee:  : Site Insp (\$) \_\_\_\_\_  
 : Interview (\$) \_\_\_\_\_  
 : Tech. Invs (\$) \_\_\_\_\_  
 : Weekend (\$) \_\_\_\_\_  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS. \$ \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL \_\_\_\_\_