

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SGN9999C
 MODEL : TOYOTA COROLLA ALTIS
 DATE OF ACCIDENT : 02.04.2022
 TIME OF ACCIDENT : 12:50HRS

26	TEMPERATURE SENSOR <i>He m</i>	1	\$ 198.40	\$ 198.40	+
27	REAR BUMPER <i>Behind</i>	1	\$ 535.90	\$ 535.90	✓
28	REAR BUMPER REFLECTOR <i>cracked</i>	2	\$ 75.10	\$ 150.20	-
29	REAR BUMPER SIDE RETAINER <i>He m</i>	2	\$ 105.10	\$ 210.20	+
30	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 395.10	\$ 395.10	✓
31	REAR BUMPER REINFORCEMENT BRACKET <i>He m</i>	2	\$ 90.10	\$ 180.20	+
32	REVERSE SENSOR <i>Damaged</i>	2	\$ 311.10	\$ 622.20	450.
33	REVERSE SENSOR HOLDER <i>He m</i>	2	\$ 69.30	\$ 138.60	50.
34	REVERSE SENSOR WIREHARNES <i>He m</i>	1	\$ 437.50	\$ 437.50	+
35	BOOTLID <i>Buckled</i>	1	\$ 756.10	\$ 756.10	-
36	BOOTLID DETECTOR <i>cracked</i>	1	\$ 385.00	\$ <u>385.00</u>	155
37	BOOTLID LOGO	1	\$ 85.00	\$ 85.00	✓
38	BOOTLID EMBLEM 'COROLLA' <i>He m</i>	1	\$ 70.00	\$ 70.00	✓
39	BOOTLID EMBLEM 'ALTIS'	1	\$ 70.00	\$ 70.00	✓
40	BOOT LID HINGE <i>He m</i>	2	\$ 70.00	\$ 140.00	+
41	BOOTLID TOP LOCK <i>Damaged</i>	1	\$ 318.10	\$ 318.10	✓
42	BOOTLID LOWER LOCK <i>He m</i>	1	\$ 20.00	\$ 20.00	+
43	BOOTLID WEATHERSTRIP <i>cut</i>	1	\$ 195.00	\$ 195.00	✓
44	TAILLAMP <i>cracked</i>	2	\$ 465.00	\$ 930.00	✓
45	TAILLAMP PANEL <i>He m</i>	2	\$ 198.00	\$ 396.00	+
46	TAILLAMP LOWER BARCKET <i>He m</i>	2	\$ 115.10	\$ 230.20	+
47	REAR FENDER INNER COWLING <i>2 He m</i>	2	\$ 350.20	\$ 700.40	+
48	REAR FENDER INNER TRIM <i>1 He m</i>	2	\$ 770.10	\$ 1,540.20	+
49	REAR END PANEL <i>Dented</i>	1	\$ 695.30	\$ 695.30	-
50	REAR END PANEL TOP GARNISH <i>Behind</i>	1	\$ 250.10	\$ 250.10	-
51	REAR FLOOR PANEL TOP BOARD <i>2</i>	1	\$ 271.10	\$ 271.10	+
52	REAR FLOOR PANEL	1	\$ 940.20	\$ 940.20	+
53	REAR FLOOR SIDE PANEL RH <i>HP</i>	1	\$ 294.60	\$ 294.60	+
54	REAR EXHAUST PIPE <i>He m</i>	1	\$ 930.20	\$ 930.20	+
55	REAR EXHAUST INSULATOR	1	\$ 147.10	\$ 147.10	+
56	REAR EXHAUST GASKET	1	\$ 80.00	\$ 80.00	+
57	REAR EXHAUST MOUNTING	4	\$ 55.10	\$ 220.40	+

16156.50 TOTAL PRICE \$ 29,855.90
 12117.37 LESS 25% \$ 7,463.98
 SUB TOTAL PRICE \$ 22,391.93

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Best</i>	1	\$ 80.00	\$ 80.00

Handwritten notes and marks on the right side of the document, including checkmarks, plus signs, and numerical values like 450, 50, 155, and 50.

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SGN9999C
 MODEL : TOYOTA COROLLA ALTIS
 DATE OF ACCIDENT : 02.04.2022
 TIME OF ACCIDENT : 12:50HRS

2	FRONT BUMPER CLIPS (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	30
3	FRONT RADIATOR GRILLE CLIP (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00	20
4	FRONT FENDER INNER COWLING CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	+
5	BONNET LOCK BRACE PANEL SEALANT <i>Neu</i>	1	\$ 80.00	\$ 80.00	+
6	BONNET INSULATOR CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	+
7	FRONT SUPPORT PANEL SEALANT <i>Neu</i>	1	\$ 100.00	\$ 100.00	+
8	RADIATOR TOP COVER GARNISH CLIP (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00	+
9	RADIATOR COOLANT <i>Neu</i>	1	\$ 60.00	\$ 60.00	40
10	REAR NUMBER PLATE <i>Neu</i>	1	\$ 80.00	\$ 80.00	+
11	REAR BUMPER CLIPS (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	30
12	BOOT LID INSULATOR CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	+
13	TAILLAMP CLIPS (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00	+
14	TAILLAMP PANEL SEALANT RH <i>Neu</i>	1	\$ 60.00	\$ 60.00	+
15	REAR FENDER COWLING CLIPS (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	+
16	REAR FENDER INNER TRIM CLIPS (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	+
17	REAR END PANEL TOP GARNISH CLIPS (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00	20
18	REAR END PANEL INSULATION SEAL <i>Neu</i>	1	\$ 150.00	\$ 150.00	60
19	REAR FLOOR PANEL INSULATION SEAL <i>Neu</i>	1	\$ 350.00	\$ 350.00	+
20	BREAKDOWN TRIANGLE SIGN <i>Neu</i>	1	\$ 180.00	\$ 180.00	+
21	REVERSE SENSOR (SET) <i>Neu</i>	1	\$ 220.00	\$ 220.00	200
22	REVERSE CAMERA <i>Neu</i>	1	\$ 450.00	\$ 450.00	+
			TOTAL	\$ 2,580.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	700
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	600
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60
5	REFOCUS HEADLAMP BEAM	\$ 60.00	30

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
-----	-----------------	-------	---------------

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SGN9999C
 MODEL : TOYOTA COROLLA ALTIS
 DATE OF ACCIDENT : 02.04.2022
 TIME OF ACCIDENT : 12:50HRS

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	800	850	20/7/22 adrian
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	800		
3	TUFF COAT	\$ 250.00	60		
4	WIRING CHECK	\$ 180.00	30		
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	60		
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50		
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50		
8	REAR CHASSIS ALIGNMENT	\$ 250.00	X		
9	TRANSFER BOOTLID MECHANISM	\$ 80.00	X		
10	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X		
11	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	\$ 80.00	X		
12	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	X		1850
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	X		

TOTAL \$ 8,370.00

TOTAL PARTS COST : \$ 24,971.93
 TOTAL LABOUR COST : \$ 8,370.00
 TOTAL REPAIR COST : \$ 33,341.93

Adrian Lj
 L/S 06/04/22.
 12 D cys.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

total: 15867.37
 L/S: 12.61c.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP:8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: