



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 4641E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT HEAD LAMP (CONSISTENT)	SERVICEABLE	2,967.10	-
1	FRONT BUMPER (CONSISTENT)	BUCKLED	1,363.23	1,363.23
1	FRONT BUMPER SIDE RETAINER (LH) (CONSISTENT)	DISTORTED	86.70	86.70
1	FRONT BUMPER LOWER PAD (CONSISTENT)	CUT	477.30	477.30
1	FRONT FENDER (LH) (CONSISTENT)	BENT	978.40	978.40
1	FRONT FENDER ARCH PROTECTOR (LH) (CONSISTENT)	DENTED	294.70	294.70
1	FRONT KNUCKLE ARM (CONSISTENT)	* CHECK	577.60	-
1	FRONT LOWER ARM (CONSISTENT)	* CHECK	476.40	-
1	FRONT STEERING TIED ROD (CONSISTENT)	SERVICEABLE	227.10	-
1	FRONT STEERING TIED ROD END (CONSISTENT)	SERVICEABLE	239.00	-
1	FRONT WHEEL BEARING (CONSISTENT)	* CHECK	341.50	-
	LESS 25% DISCOUNT		-2,007.26	-800.08
			6,021.77	2,400.25
<b><u>SPECIAL NETT ITEMS</u></b>				
1	ALLOY RIM (SN) (CONSISTENT)	DENTED	680.00	680.00
			680.00	680.00
<b><u>LABOUR</u></b>				
	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE ,KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS .		2,400.00	400.00
	TO CHECK WIRING SYSTEM.		50.00	20.00
	TO SPRAY PAINTING ON AFFECTED AREAS .		600.00	400.00
	TO CHARGE ALLOY RIM AND BALANCE WHEEL .		40.00	20.00
	TO CHECK WHEEL ALIGNMENT (4 WHEEL).		85.00	60.00
	TO REPLACE UNDERCARRIAGE PARTS AND MACHINE PRESS WHEEL BEARING.	* CHECK	260.00	-
			3,435.00	900.00
<b>GRAND TOTAL</b>			<b>10,136.77</b>	<b>3,980.25</b>



<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,306.63 NETT)</b>			<b>3,980.25</b>
--	--	--	-----------------

Report Ref No. CC4/ASM22003138/Kea3q2

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**