



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22003141/Bvy3s2	
			Date: 20/04/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMB 3533U	Veh. Inspected	SJM 7680D	
Policy No.		Coverage (\$)	0.00	
Claim No.	NC-22002098	Excess (\$)	0.00	
Assign From	HARMINDER KAUR	Assign Date	05/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY 2.0	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MR053BK4107038318	Colour	SILVER	
Odometer	203379 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/ 60R16	DUNLOP	5 mm	
L/H Front Tyre	215/ 60R16	DUNLOP	5 mm	
R/H Rear Tyre	215/ 60R16	DUNLOP	5 mm	
L/H Rear Tyre	215/ 60R16	DUNLOP	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/04/2022	Inspection Date	06/04/2022	
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	