



# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

**M/S :** AIG ASIA PACIFIC INSURANCE PTE LTD  
 78 SHENTON WAY  
 #07-16 AIG BUILDING  
 SINGAPORE 079120

**Estimate No:** ES2290499/YISHUN  
**Date:** 20 May 2022

**TEL:** 64193000  
**ATTN:** Motor Claim Department  
**WS Ref:** TP AIG

**FAX:** 64153727

**Policy No:**  
**Veh Reg No:** GBE2260C  
**Make/Model:** TOYOTA DYNA 150 D  
**Chassis No:** JTFAT35YX0K205056  
**Engine No:** 1KD2557144  
**Reg. Date:** 02/10/2015

**Claim Type:** Third Party  
**Accident Date:** 01/04/2022  
**TP Veh Reg No:** GBG1527E

*Not authorized*  
*11 PM @*  
*Meowny After Rain*  
*6 days*

### Estimate Repair Cost to Vehicle No :GBE2260C

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
<b>List Price</b>				
1 REAR TAILGATE	1,185.00	1 PC	1,185.00	✓
2 REAR TAILGATE LOCK RH	100.30	1 PC	100.30	✓
3 RER TAILGATE LOCK HANDLE RH	66.70	1 PC	66.70	✓
4 TAILLAMP RH	221.90	1 PC	221.90	✓
5 TAILLAMP PANEL RH	64.70	1 PC	64.70	✓
6 RH SIDE GATE LOCK	1,492.20	1 PC	1,492.20	✓
			3,130.80	
		Less 25%	782.70	2,348.10
<b>Special Net</b>				
7 STICKER - 13PAX	12.00	1 PC	12.00	✓
8 STICKER- 70km/h	12.00	1 PC	12.00	✓
9 TAILGATE INNER PROTECTOR	280.00	1 PC	280.00	✓
10 TAILGATE INNER PROTECTOR RIVET	3.00	18 PCS	54.00	✓
11 REVERSE CAMERA	200.00	1 PC	200.00	?
12 REAR NUMBER PLATE	20.00	1 PC	20.00	X
13 REAR CORNAL STOPPER RH	22.00	1 PC	22.00	✓
14 REAR RH SIDE GATE INNER PROTECTOR	350.00	1 PC	350.00	✓
15 REAR RH SIDE GATE INNER PROTECTOR RIVET	3.00	18 PCS	54.00	✓
16 REAR FLOOR BOARD PROTECTOR	600.00	1 PC	600.00	?
			1,604.00	1,604.00
<b>Labour</b>				
17 TO REMVOE AND REFIX REAR FULL CANOPY, FLOOR BOARD PROTECTOR, RR TRUCK ASSY; TO CUT, WELD, KNOCK & REPAIR RR END MEMBER, TAILGATE LOWER PANEL, RH SIDE PANEL, CABIN RR RH PILLAR AND RE-ALIGN TO SAME	1,000.00	1 LA	1,000.00	850
18 TO PUTTY AND RESPRAY ON TAILGATE, RH SIDE GATE, LOWER MEMBER, RR FLOOR BOARD PANEL, RR END MEMBER, RH PILLAR AND ALL AFFECTED PARTS	1,000.00	1 LA	1,000.00	800
19 TO REWRITE ADVERTISEMENT	350.00	1 LA	350.00	?
20 TO REPAR, RE-ALIGN REAR CANOPY	200.00	1 LA	200.00	180
			2,550.00	2,550.00

**KK Auto Consultants hence notify the Repairer of the following:**  
 • To resurvey before/after spray painting  
 • To display damaged part(s) for resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 04/04/2022 18:09 (SGT)  
Date of Accident ..... 01/04/2022 10:10 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... SUNGEI KADUT 1  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... GBE2260C

### INSURED/POLICYHOLDER

Is company? ..... Yes  
Name Of Registered Owner ..... HOCK UNITED ENGINEERING PTE LTD  
Company Reg No ..... 2XXXXX132D  
Email Address ..... admin@hue.com.sg  
Mobile Phone No ..... (Phone) +65-63632313  
Alternative Phone No ..... (Office) +65-63632313

### VEHICLE PARTICULARS

Manufacturer ..... Toyota  
Model ..... TOYOTA DYNA 150 MANUAL  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Employment  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Commercial vehicle  
Transmission ..... Manual  
CC ..... 2982

### INSURANCE COMPANY

Name of Insurance Company ..... Tokio Marine Insurance Singapore Ltd  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... 21-MS010885-R02  
Cover Note Number ..... 2/10/21-1/10/22

### DRIVER

Name of Driver ..... HOSSAIN MOHAMMED JAKIR  
Passport No/FIN ..... GXXXX298R

