

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

**M/S :** AIG ASIA PACIFIC INSURANCE PTE LTD  
 78 SHENTON WAY  
 #07-16 AIG BUILDING  
 SINGAPORE 079120

**Estimate No:** ES2290499/YISHUN  
**Date:** 20 May 2022

TEL: 64193000 FAX: 64153727

**Policy No:**  
**Veh Reg No:** GBE2260C

ATTN: Motor Claim Department

*Not authorized*

**Make/Model:** TOYOTA DYNA 150 D

WS Ref: TP AIG

**Chassis No:** JTFAT35YX0K205056

Claim Type: Third Party

*11 Pm @ 4600h*

**Engine No:** 1KD2557144

Accident Date: 01/04/2022

*Permy After Rain*

**Reg. Date:** 02/10/2015

TP Veh Reg No: GBG1527E

*6 days*

## Estimate Repair Cost to Vehicle No :GBE2260C

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
<b>List Price</b>				
1 REAR TAILGATE <i>1185</i>	1,185.00	1 PC	<i>Bj</i> 1,185.00	✓
2 REAR TAILGATE LOCK RH	100.30	1 PC	<i>Bj</i> 100.30	✓
3 RER TAILGATE LOCK HANDLE RH	66.70	1 PC	<i>Mi</i> 66.70	✓
4 TAILLAMP RH	221.90	1 PC	<i>CM</i> 221.90	✓
5 TAILLAMP PANEL RH	64.70	1 PC	<i>Bj</i> 64.70	✓
6 RH SIDE GATE <i>1492.20</i>	1,492.20	1 PC	<i>Bj</i> 1,492.20	✓
			3,130.80	
		Less 25%	782.70	2,348.10
<b>Special Net</b>				
7 STICKER - 13PAX	12.00	1 PC	<i>Mu</i> 12.00	✓
8 STICKER- 70km/h	12.00	1 PC	<i>Mu</i> 12.00	✓
9 TAILGATE INNER PROTECTOR	280.00	1 PC	<i>Mu</i> 280.00	✓
10 TAILGATE INNER PROTECTOR RIVET	3.00	18 PCS	<i>Mu</i> 54.00	✓
11 REVERSE CAMERA	200.00	1 PC	<i>Su</i> 200.00	X
12 REAR NUMBER PLATE	20.00	1 PC	<i>Su</i> 20.00	X
13 REAR CORNAL STOPPER RH	22.00	1 PC	<i>Mi</i> 22.00	✓
14 REAR RH SIDE GATE INNER PROTECTOR	350.00	1 PC	<i>Mu</i> 350.00	✓
15 REAR RH SIDE GATE INNER PROTECTOR RIVET	3.00	18 PCS	<i>Mu</i> 54.00	✓
16 REAR FLOOR BOARD PROTECTOR	600.00	1 PC	<i>Bj</i> 600.00	✓
			1,604.00	1,604.00
<b>Labour</b>				
17 TO REMVOE AND REFIX REAR FULL CANOPY, FLOOR BOARD PROTECTOR, RR TRUCK ASSY; TO CUT, WELD, KNOCK & REPAIR RR END MEMBER, TAILGATE LOWER PANEL, RHSIDE PANEL, CABIN RR RH PILLAR AND RE-ALIGN TO SAME	1,000.00	1 LA	1,000.00	<i>850</i>
18 TO PUTTY AND RESPRAY ON TAILGATE, RH SIDE GATE, LOWER MEMBER, RR FLOOR BOARD PANEL, CABIN RR PANEL, RH PILLAR AND ALL AFFECTED PARTS	1,000.00	1 LA	1,000.00	<i>800</i>
19 TO REWRITE ADVERTISEMENT	350.00	1 LA	350.00	<i>220</i>
20 TO REPAR, RE-ALIGN REAR CANOPY	200.00	1 LA	200.00	<i>180</i>
			2,550.00	2,550.00

**Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*(Bill)* 350.00 *220*  
 200.00 *180*  
 2,550.00 *2,550.00*

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

**M/S :** AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
TEL: 64193000 FAX: 64153727  
ATTN: Motor Claim Department  
WS Ref: TP AIG  
Claim Type: Third Party  
Accident Date: 01/04/2022  
TP Veh Reg No: GBG1527E

**Estimate No:** ES2290499/YISHUN  
**Date:** 20 May 2022  
**Policy No:**  
**Veh Reg No:** GBE2260C  
**Make/Model:** TOYOTA DYNA 150 D  
**Chassis No:** JTFAT35YX0K205056  
**Engine No:** 1KD2557144  
**Reg. Date:** 02/10/2015

## Estimate Repair Cost to Vehicle No :GBE2260C

<u>Description</u>	<u>U/Price</u>	<u>Quantity</u>	<u>List Price</u>	<u>Amount</u>
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 6,502.10
			Add GST @ 7%	455.15
			Total Amount Payable	<u>S\$ 6,957.25</u>

**For Cheng Hoe Motor Pte Ltd**

\_\_\_\_\_  
AUTHORISED SIGNATURE