

KS AUTOMOBILE
(COMPANY REG:53433258K)
60 JALAN LAM HUAT, CARROS CENTRE
#05-68 (S737869)
Tel: 93911482 (DAUD)

TO	: CHINA TAIPING	DATE	: 6-Apr-22
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
Veron		<u>VEHICLE DETAILS</u>	
:		VEHICLE NO	: GBG5440U
:		MODEL	: TOYOTA HIACE

QUOTATION SUMMARY

JTFHT02P000231881

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE Distorted	1	\$ 1,754.00	\$ 1,754.00
2	TAILGATE OUTER HANDLE New	1	\$ 194.20	\$ 194.20
3	TAILGATE OUTER MOULDING Cut	1	\$ 312.00	\$ 312.00
4	TAILGATE NUMBER PLATE LAMP New	2	\$ 59.60	\$ 119.20
5	TAILGATE INNER TRIM Not New	1	\$ 267.60	\$ 267.60
6	TAILGATE WEATHERSTRIP New	1	\$ 368.00	\$ 368.00
7	TAILGATE WEATHERSTRIP PROTECTOR New	1	\$ 99.60	\$ 99.60
8	TAILGATE INNER LOCK Jammed	1	\$ 257.60	\$ 257.60
9	TAILGATE LOWER LOCK Jammed	1	\$ 100.20	\$ 100.20
10	TAILGATE KEY LOCK Not New	1	\$ 241.60	\$ 241.60
11	TAILGATE WINDSCREEN RUBBER New	1	\$ 294.00	\$ 294.00
12	TAILGATE LOGO New	1	\$ 59.00	\$ 59.00
13	TAILGATE INNER TOP TRAM New	1	\$ 284.00	\$ 284.00
14	TAIL GATE CAMERA New	1	\$ 845.00	\$ 845.00
15	TAIL LAMP Cracked	2	\$ 297.60	\$ 595.20
16	TAIL LAMP PANEL RH & Repair	1	\$ 387.90	\$ 387.90
17	REAR FLOOR MAT Not New	1	\$ 800.00	\$ 800.00
18	REAR BUMPER Distorted	1	\$ 598.00	\$ 598.00
19	REAR BUMPER SIDE RETAINER New	2	\$ 67.20	\$ 134.40
20	REAR FENDER INNER PANEL Repair	1	\$ 679.40	\$ 679.40

21	REAR END PANEL (INNER) <i>Repis</i>	1	\$ 547.10	\$ 547.10
22	REAR END PANEL (OUTER) <i>Dented</i>	1	\$ 850.20	\$ 850.20
23	REAR END PANEL EXTEND PANEL <i>RH Dented</i>	2	\$ 398.70	\$ 797.40
24	REAR FLOOR PANEL <i>Repis</i>	1	\$ 2,295.00	\$ 2,298.00
25	REAR EXHAUST PIPE <i>2 1/4"</i>	1	\$ 898.00	\$ 898.00
26	REAR EXHAUST PIPE MOUNTING <i>7 1/2"</i>	2	\$ 28.00	\$ 56.00

5047.90
3785.92

TOTAL PRICE \$ 13,837.60
LESS 25% \$ 3,459.40
SUB TOTAL PRICE \$ 10,378.20

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Bent</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP <i>Nec</i>	8	\$ 6.50	\$ 52.00
3	REAR REVERSE SENSOR <i>Damaged</i>	1	\$ 250.00	\$ 250.00
4	TAILGATE INNER BOARD CLIP <i>Nec</i>	8	\$ 6.50	\$ 52.00
5	TAILGATE SEALANT <i>Nec</i>	1	\$ 80.00	\$ 80.00
6	TAILGATE STICKER '70km/h' <i>Nec</i>	1	\$ 20.00	\$ 20.00
7	TAILGATE STICKER '8PAX' <i>Nec</i>	1	\$ 20.00	\$ 20.00
8	TAILGATE COMPANY STICKER SET <i>Nec</i>	1	\$ 200.00	\$ 200.00
9	REAR END PANEL SEALANT <i>Nec</i>	1	\$ 80.00	\$ 80.00
10	REAR END PANEL TOP PLATE <i>2 1/2"</i>	1	\$ 300.00	\$ 300.00
11	REAR END PANEL EXTEND PANEL SEALANT <i>Nec</i>	1	\$ 80.00	\$ 80.00
12	REAR FLOOR PANEL TOP WOODEN (SPECIAL TYPE)	1	\$ 600.00	\$ 600.00
13	REAR FENDER INNER PANEL SEALANT <i>Nec</i>	1	\$ 80.00	\$ 80.00
14	REAR FLOOR PANEL SEALANT <i>2 1/2"</i>	1	\$ 100.00	\$ 100.00
15	REAR FLOOR TOP BOARD <i>7 1/2"</i>	1	\$ 800.00	\$ 800.00
16	REAR FLOOR PANEL SEALANT <i>7 1/2"</i>	1	\$ 300.00	\$ 300.00

TOTAL \$ 3,064.00

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING AND REPLACE PARTS	\$1,600.00	800	
2	SPRAY PAINTING TO AFFECTED AREA	\$1,400.00	800	
3	TUFF COAT	\$250.00	80	

4	WIRNING, BULB CHECKING	\$80.00	X	
5	REMOVE AND REFIX TAILGATE WINDSCREEN	\$150.00	120	
6	TRANSFER TAILGATE MECHAISM	\$120.00	60	
7	CONDUCT WATER LEAKAGE TEST	\$100.00	X	
8	REMOVE AND REFIX REAR EXHAUST	\$150.00	X	
9	REAR CHASSIS ALIGHMENT	\$250.00	X	

TOTAL

\$4,100.00

1860

ESTIMATE REPORT

TOTAL PARTS COST : \$ 13,442.20
TOTAL LABOUR COST : \$ 4,100.00
TOTAL REPAIR COST : \$ 17,542.20

Adrian King,

L/S 06/04/22

06 Days

Total: 6145.92

L/S: 4.9K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: