

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2204-188 TG

DATE : 5-Apr-2022

POLICY NO. : PNPV2019-00004946-01

VEHICLE REG. NO. : SKM5017J

VEHICLE MAKE : SUBARU FORESTER 2.0XT CVT AWD SR

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper	1	\$ 550.00	\$ 550.00
2	Rear Bumper Clips	10	\$ 5.00	\$ 50.00
3	Rear Bumper Bracket	1	\$ 25.00	\$ 25.00
4	Rear Bumper Retainer RH	1	\$ 20.00	\$ 20.00
5	Rear Bumper Retainer LH	1	\$ 20.00	\$ 20.00
6	Rear Reinforcement	1	\$ 350.00	\$ 350.00
7	Rear Bumper Reflector RH	1	\$ 38.00	\$ 38.00
8	Rear Bumper Reflector LH	1	\$ 38.00	\$ 38.00
9	Tail Lamp RH	1	\$ 480.00	\$ 480.00
10	Tail Lamp LH	1	\$ 480.00	\$ 480.00
11	Tail Lamp Special Clips	4	\$ 6.00	\$ 24.00
12	Tailgate	1	\$ 1,280.00	\$ 1,280.00
13	Tailgate Hinge RH	1	\$ 50.00	\$ 50.00
14	Tailgate Hinge LH	1	\$ 50.00	\$ 50.00
15	Tailgate Absorber RH	1	\$ 195.00	\$ 195.00
16	Tailgate Absorber LH	1	\$ 195.00	\$ 195.00
17	Tailgate Lock	1	\$ 560.00	\$ 560.00
18	Tailgate Striker	1	\$ 35.00	\$ 35.00
19	Tailgate Switch Opener Assy - 63270SG010	1	\$ 110.00	\$ 110.00
20	Tailgate Rubber Seal	1	\$ 135.00	\$ 135.00
21	Tailgate Upper Trim Garnish	1	\$ 270.00	\$ 270.00
22	Tailgate Upper Trim Garnish Special Clips	14	\$ 7.00	\$ 98.00
23	Tailgate Spoiler	1	\$ 880.00	\$ 880.00
24	Tailgate Lower Inner Trim	1	\$ 250.00	\$ 250.00
25	Tailgate Upper Inner Trim	1	\$ 90.00	\$ 90.00
26	Rear Subaru & AWD Emblem	1	\$ 90.00	\$ 90.00
27	Rear Forester XT Emblem	1	\$ 90.00	\$ 90.00
28	Rear Windscreen Wiper Motor	1	\$ 290.00	\$ 290.00
29	Rear Windscreen Wiper Arm	1	\$ 68.00	\$ 68.00
30	Rear Windscreen Wiper Blade	1	\$ 45.00	\$ 45.00
31	Rear Windscreen Wiper Cover	1	\$ 15.00	\$ 15.00
32	Rear Windscreen	1	\$ 1,450.00	\$ 1,450.00

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2204-188 TG
DATE : 5-Apr-2022
POLICY NO. : PNPV2019-00004946-01
VEHICLE REG. NO. : SKM5017J
VEHICLE MAKE : SUBARU FORESTER 2.0XT CVT AWD SRTO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
33	Rear Windscreen Moulding Assy	1	\$ 70.00	\$ 70.00
34	End Panel Top Garnish	1	\$ 60.00	\$ 60.00
35	End Panel	1	\$ 350.00	\$ 350.00
36	Spare Tyre Board	1	\$ 280.00	\$ 280.00
37	Rear Floor Panel	1	\$ 450.00	\$ 450.00
Total Spare Parts				\$ 9,531.00
	<u>SPECIAL NETT</u>			
38	Rear License Plate with Casing	1	\$ 40.00	\$ 40.00
39	Reverse Sensor	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 240.00
	<u>LABOUR</u>			
40	Spray Paint (Whole Rear, Inner Panels & Roof Panel)	1	\$ 1,400.00	\$ 1,400.00
41	Remove, Refit, Repair and Replace Accident Affected Parts	1	\$ 1,000.00	\$ 1,000.00
42	Transfer Tailgate Fitting & Window Mechanism to New Tailgate	1	\$ 100.00	\$ 100.00
43	Remove & Refit Upholstery, Garnishes, Trimming To Facilitate Repair	1	\$ 250.00	\$ 250.00
44	Computerized Wheel Alignment	1	\$ 80.00	\$ 80.00
45	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
46	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,960.00
Amount Before Excess				\$ 12,731.00
Add GST @ 7%				891.17
Total Amount Payable				\$ 13,622.17

Estimate prepared by: Ken Ho

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.