



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SLS1855B
Chassis No : JHMR1890HC203471
Model : ODYSSEY 2.4 EXV-S 17YM (EURO 6)
Owner's Name : KOH THIEM TECK
Ins Policy No. :
Date of Accident : 30/3/2022

Document No. : SQT22000890
Date : 1. Apr 2022
Customer No. : WZL009
Svc Advisor : IVAN TEO BOON KIAT
Engine No : K24W72041114
Date | Time : 1. Apr 2022 12:08:11 PM

Page 1

LKK Auto Consultants hence notify the Repairer of the following:
Authorisation Date:

- To resurvey before/after spray painting
- To display (if not part(s) during resurvey
- Parts to be subject to confirmation
- Third party survey Unit Price in Discrepancy Amount
- No illegal modification is allowed
- Supplementary claims must be reviewed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

0% GST Amount
Amount incld GST

Item	Description	Qty	Unit Price	Disc/Adj	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: KOH THIEM TECK OWNER INSURER: SINGAPORE LIFE LTD ACC DATE: 30/03/2022 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC TP VEH: XD3894L						
67050-T6A-000ZZ	PANEL COMPL.FR.DOOR / BT	1	954.70	25	716.02	50.12	766.14
67364-T6A-305ZA	TAPE SETL.FR.DOOR SASH INNER / nbc	1	40.90	25	30.67	2.15	32.82
67550-T6A-J00ZZ	PANEL COMPL.SLIDE DOOR / nbc	1	1067.00	25	800.25	56.02	856.27
67861-T6A-305ZA	TAPE SETL.RR.DOOR SASH INNER / nbc	1	60.90	25	45.67	3.20	48.87
72450-T6A-003	MOLDING ASSYL.FR.DOOR = 1 nbc	1	78.80	25	59.10	4.14	63.24
72950-T6A-003	MOLDING ASSYL.RR.DOOR = 1 nbc	1	74.20	25	55.65	3.90	59.55
72181-T6A-J71	HANDLE COMPL.FR. 2 = 1 nbc	1	336.90	25	252.67	17.69	270.36
72183-SZW-J01	COVER COMPL.FR. 2 = 1 nbc	1	43.00	25	32.25	2.26	34.51
72681-SZW-J01	HANDLE COMPL.RR. = 1 nbc	1	76.00	25	57.00	3.99	60.99
72683-SZW-J01	COVER COMPL.RR. = 1 nbc	1	40.50	25	30.37	2.13	32.50
72682-T6A-A71	BASE COMPL.RR. ? = 1 nbc	1	48.70	25	36.52	2.56	39.08
75332-T6A-J11ZG	GARNISH ASSYL.FR.DOOR LOWER = 1 nbc	1	308.90	25	231.67	16.22	247.89
75333-T6A-J11ZD	GARNISH ASSYL.SLIDE DOOR LWR = 1 nbc	1	290.10	25	217.57	15.23	232.80
Sum Item					2565.41	179.61	2,745.02
BOSUN	SUNDRIES	1	60.00	40	60.00	4.20	64.20
BKDR11R	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST	1	300.00	✓	300.00	21.00	321.00
BKDR31R	REMOVE & TRANSFER ITEMS TO NEW RR L SLIDING DR.	1	650.00	✓	650.00	45.50	695.50

Printed on 1/4/2022 1:19:59 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838
For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Website: www.honda.com.sg

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SLS1855B
Chassis No : JHMRC1890HC203471
Model : ODYSSEY 2.4 EXV-S 17YM (EURO 6)
Owner's Name : KOH THIEM TECK
Ins Policy No. :
Date of Accident : 30/3/2022

Document No. : SQT22000890 **Page** 2
Date : 1. Apr 2022
Customer No. : WZL009
Svc Advisor : IVAN TEO BOON KIAT
Engine No : K24W72041114
Date | Time : 1. Apr 2022 12:08:11 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOJSE	APPLY DOOR JOINT SEALANT.(NETT)	1	200.00	✓	200.00	14.00	214.00
BKCP11R	STRAIGHTEN & KNOCKOUT CTR PILLAR OUTER PANEL,	650 ₁	1500.00	1300	1500.00	105.00	1605.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.	1	1800.00	1080.	1800.00	126.00	1926.00
		5740	Sum Labor		4510.00	315.70	4,825.70

Survey By Gino Qian
Date & Time 82880282 **Total Amount** 7,075.41 495.31 7,570.72
Excess Gino Qian @ Kkanto car **Total (Inclusive of GST)** 7,570.72
Status _____
Signature _____

11/4/22.
5 Pays
before paint photos.

Printed on 1/4/2022 1:19:59 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.