



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|---|-------------------------------|--------------------|
| LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555 | | | Ref: CS3/LPC21012354/Vty3e2-1 | |
| | | | Date: 23/06/2022 | |
| | | | Code: LPC2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | XE 952S | Veh. Inspected | SKF 821K |
| | Policy No. | Z/21/VC06/111964 | Coverage (\$) | 0.00 |
| | Claim No. | 21/21/21/VC06/025218 | Excess (\$) | 0.00 |
| | Assign From | Ong Li Li | Assign Date | 05/04/2022 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | TOYOTA COROLLA ALTIS | c.c | 1598 |
| | Engine No. | HIDDEN | Year of Reg. | 2016 |
| | Chassis No. | MR053REH104557651 | Colour | WHITE |
| | Odometer | 102833 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 215/45Z R17 | MICHELIN | 6 mm |
| | L/H Front Tyre | 215/45Z R17 | MICHELIN | 6 mm |
| | R/H Rear Tyre | 215/45Z R17 | MICHELIN | 6 mm |
| | L/H Rear Tyre | 215/45Z R17 | MICHELIN | 6 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 30/11/2021 | Inspection Date | 07/12/2021 |
| | Survey held at | GFORCE AUTOTECH PTD LTD 10 KAKI BUKIT ROAD 2 #01-34 FIRST EAST CENTRE SINGAPORE 417868 | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 4 Working Days | |