

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **Allianz Global Corporate & Specialty SE, Singapore Branch**

SPMF1000000449

Policy No: _____

04.04.2022

Date: _____

Accident Date : 29.03.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Honda Shuttle Hybrid" Reg. No SLZ4320X			
1pc	Bonnet		480.00
2pcs	Bonnet Hinges	22.00	44.00
1pc	Bonnet Lock		85.00
1pc	Bonnet Rubber Seal		20.00
1pc	Bonnet Insulator		80.00
5pcs	Bonnet Insulator Clips	3.50	17.50
1pc	Grille		160.00
1pc	Grille Emblem		16.00
1pc	Grille Emblem Brace Bracket		35.00
1pc	Grille Outer Chrome Cover		160.00
1pc	Grille Lower Chrome Moulding		100.00
1pc	Grille Top Brace Bracket		75.00
2pcs	Grille Side Brackets	35.00	70.00
2pcs	Headlamps (LED)	1,300.00	2,600.00
1pc	Front Bumper		480.00
10pcs	Front Bumper Clips	3.50	35.00
1pc	Front Bumper Reinforcement		210.00
1pc	Front Bumper Center Air Grille		65.00
2pcs	Front Bumper Corner Retainers	6.00	12.00
1pc	Front Bumper Tow Point Cover		12.00
2pcs	Front Bumper Fog Lamps	160.00	320.00
1pc	Front Bumper Fog Lamp Wiring Harness		462.00
1pc	Front Bumper Fog Lamp Cover		55.00
2pcs	Front Bumper Fog Lamp Cover Chrome Mouldings	65.00	130.00
1pc	Front Bumper Fog Lamp Top Garnish RH		65.00
1pc	Front Fender RH		140.00
1pc	Front Fender Shield		80.00
1pc	Front Fender Badge Hybrid		95.00
1pc	Support Panel		370.00
1pc	Support Panel Top Garnish		35.00
1pc	Air Con Condenser		650.00
1pc	Air Con Condenser Side Air Guide		25.00
1pc	Radiator		750.00
1pc	Front Exterior Ambience Sensor		35.00
1pc	Air Cleaner Cold Intake Air Duct		75.00
			8,043.50
	Cost Plus 10%		804.35
			8,847.85
		C/F	8,847.85

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **Allianz Global Corporate & Specialty SE, Singapore Branch**

Policy No: **SPMF1000000449**

Accident Date : **29.03.2022**

Date: **04.04.2022**

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数 量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Honda Shuttle Hybrid" Reg. No SLZ4320X		
		B/F	8,847.85
	To Conduct Electrical Check, Focus Headlamp		30.00
	To Remove / Refit Air Con Condenser & Refill Air Con Gas		120.00
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		60.00
	To Provide Transportation (Towing)		120.00
	Labour Charge - Panel Beating, Repairing Front Chassis, Front LH Fender, Windscreen Pillar.Cnt, Weld Support & Part Replacement		800.00
	To Respray Affected Areas		950.00
		Total :	10,927.85