

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO **SHA3481A**

02.04.2022

MAKE **REG: 10.03.2016**

MODEL **HYU- I40**

Type **CHIANG/ NTUC**

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER COVER		\$553.00
1	REAR BUMPER LOWER COVER		\$228.00
10	REAR BUMPER CLIPS	\$2.20	\$22.00
1	REAR BUMPER BRACKET RH		\$35.60
1	REAR BUMPER REINFORCEMENT		\$428.40
1	REAR BUMPER REFLECTOR RH		\$32.00
	SUB TOTAL		\$1,299.00
	20.00%		\$259.80
	DISCOUNTED TOTAL		\$1,039.20
1	REAR REVERSE SENSOR		\$135.70
			\$122.13
	Labour Charge		
	Panel Beating		\$560.00
	Spray Painting Charge		\$300.00
	Remove/refix reverse sensor		\$60.00
	Check Lighting & Wiring		\$40.00
	TOTAL LABOUR		\$960.00
	ESTIMATE TOTAL		\$2,121.33

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thevan
 82235769
 1600 4/3/22
 Zelaya wp
 4578 LIS repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: