

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122003160/VQY3N2**Date:** 29/04/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SHA3646S**Insured Vehicle No :** GBD8918E

Date of Loss: 04/04/2022

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHA3646S**

Make & Model: HYUNDAI AE IONIQ, 1.6 (A)

Engine No: G4LEJU189551

Reg. Date: 01/03/2019 (Man. Year: 2018)

Chassis No: KMHC851CVKU141168

Colour: Blue

Odometer: 405652 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size: 195/65R15

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,398.52	1,398.52	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	1,000.00	300.00	23.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,698.52	2,398.52	300.00	11.12
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	2,698.52	1,900.00	798.52	29.59
+ GST 7.00/7.00% (S\$)	188.90	133.00	55.90	29.59
Nett Amount (S\$)	2,887.42	2,033.00	854.42	29.59

INSPECTION

Date of Assignment: 05/04/2022

Date Inspected: 06/04/2022 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2022)
Parts:	143	HYUNDAI AE IONIQ 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA3646S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WING MIRROR LH	Scratched	1,391.70 FL	*1,391.70 FL
2	1		*FRT FENDER BLUE DRIVE LH	Necessary	26.60 FL	*26.60 FL
3	1		*FRT WHEEL CAP LH	Scratched	346.40 FL	*346.40 FL
4	1		*FRT DR COMFORTDELGRO LH	Necessary	75.00 FS	*75.00 FS
					Sub Total (\$)	1,839.70
					- List Item Discount on L Items 25.00/25.00% (\$)	441.18
					Total Parts (\$)	1,398.52

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAYPAINT CHARGE	New	900.00	650.00
2	PANEL BEATING	New	400.00	350.00
Gross Labour Cost (S\$)			1,300.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >