

Our Job Ref No : 305511394

Date : 07/04/22

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr Thevan

Vehicle Reg No. : SHD4133H

04/04/2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SLU4108U
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost \$0.00
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost \$3,050.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Ms. Loke YY

Tel : 62148355

Fax : 65468156

Signature : 

Name : Thevan

Date : 22/4/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORT DELGRO ENGINEERING

VEHICLE I SHD4133H

NTUC

305511394

TYPE OF C: TP

SURVEY B': LKK/THEVAN

DATE : 07/04/22

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

DESCRIPTION	QTY	ESTIMATE	\$	REMARKS
AIRCON CONDENSER	1		\$663.60	/Cut
AIRCON TUBE LIQUID	1		\$224.00	/Cut
ACTIVE AIR UPPER FLAP ASSY RI1	1		\$168.00	/Cut
		TOTAL	\$1,055.60	

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD4133H

Date: 04.04.2022

Make : HYUNDAI

Insurance: NTUC

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
	RADIATOR GRILLE			\$ 1,409.10
	FRT NUMBER PLATE GARNISH			\$ 188.00
	UNIT ASSY SMART CRUISE RADAR SENSOR			\$ 2,910.90
	FRT BUMPER			\$ 430.90
	FRT BUMPER REINFORCEMENT			\$ 1,075.10
	FRT BUMPER REINFORCEMENT ABSORBER LH RH		\$ 93.25	\$ 186.50
	FRT BUMPER MOULDING CENTRE UPPER			\$ 368.50
	FRT BUMPER BRACKET TOP LH RH		\$ 35.00	\$ 70.00
	FRT BUMPER SIDE BRACKET LH RH.			\$ 56.00
	FRT BUMPER CLIPS			\$ 22.00
	FRT BUMPER CENTRE GRILLE			\$ 318.80
	FRT BUMPER LOWER GRILLE MOULDING			\$ 127.60
	HEADLAMP SUPPORT PANEL ASSY			\$ 949.30
	SUB TOTAL			\$ 8,112.70
	LESS 20%			\$ 1,622.54
	DISCOUNTED TOTAL			\$ 6,490.16
1	FRT NUMBER PLATE WITH TRIM COVER			\$ 55.00
				\$ 55.00
	Labour Charge			
	PANEL BEATING			\$ 1,100.00
	SPRAY PAINTING CHARGE			\$ 300.00
	TOTAL LABOUR			\$ 1,400.00
	Emblem-Blue Drive (LH/RH)			
	ESTIMATE TOTAL			\$ 7,945.16

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thevan
 92235769
 4/4/22 1730
 L/S repair
 delays w/p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer