

Our Job Ref No : 305511390
Date : 06/04/22

COMFORTDELGRO
ENGINEERING

ComfortDaiGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr Thevan
Vehicle Reg No. : SHA4179S CTPL

Fax :

04/04/2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: **NTUC** --- **FZ4790T**
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges


Total for Part-By-Part Repair Cost **\$0.00**

 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost **\$700.00**

3. Estimated normal period for repairs: 1 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : Ms. Loke YY
Tel : 62148355
Fax : 65468156

Signature : 
Name : Thevan
Date : 26/4/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA4179S

Date: 04/04/22

Make : HYUNDAI

Insurance: NTUC

Model : I-40

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	FRT DOOR MIRROR RH			\$ 670.00	CV9
	SUB TOTAL			\$ 670.00	
	LESS 20%			\$ 134.00	
	DISCOUNTED TOTAL			\$ 536.00	
					Nett
					Nett
				\$ -	Nett
	Labour Charge				
	PANEL BEATING			\$ 150.00	
	SPRAY PAINTING CHARGE			\$ 150.00	
	CHECK WIRING AND LIGHTING			\$ 30.00	
	TOTAL LABOUR			\$ 330.00	
	ESTIMATE TOTAL			\$ 866.00	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Therav
82235769
4/4/22 1615
L/S repair
1 clay swp

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: