



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22003164/Tty3n2	
			Date: 04/05/2022	
			Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLR 4559S	Veh. Inspected	SLU 9532U
	Policy No.		Coverage (\$)	0.00
	Claim No.	2022 22004403SL	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	05/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS HYBRID	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTDKB3FU003564857	Colour	WHITE
	Odometer	248558 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	DUNLOP	6 mm
	L/H Front Tyre	195/65 R15	DUNLOP	6 mm
	R/H Rear Tyre	195/65 R15	DUNLOP	6 mm
	L/H Rear Tyre	195/65 R15	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/04/2022	Inspection Date	06/04/2022
	Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	