



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd				
		Document No. 0	3 Media Close #07-03 Singapore 138498				
		Document Date 04/04/2022	Work: 65703925				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	19/12/2017	SLU9532U	0	14332	66TP/SLU9532U/040422
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU003564857		2ZRS065682	60	Shashitharan	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SLR4559S ACC DATE:040422 DRIVE IN:04/04/22 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				✓ 50.	100.00
2	B	BP-LAB2 CHECK WIRIN GAND CONDUCT REFOCUS HEADLAM P				✓ ✓	180.00
3	B	BP-LAB2 REPL ACC AFF PARTS ANDPANEL STRAIGHTEN AND REALIGN ACC AFF AREA FRT PORTION				✓ 1080	2160.00
4	B	BP-RES2 RESRPAY ACC AFF AREA FRT PORTION				✓ 1180.	1770.00
5	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SESNOR RE AR PORTION				✓ ✓	180.00
6	B	BP-LAB2 CONDUCT LEAK TEST REST REAR PORTION				✓ ✓	180.00
7	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA REEAR PORTION				✓ 720	1440.00
8	B	BP-RES2 RESRPAY ACC AFF AREA REAR PORTION				✓ 590	1180.00
9	1	U53395-47040 SEAL, HOOD TO FR END	1.00	54.70		rel ✓	54.70 ✓
10	2	U52119-47962 COVER, FR BUMPER	1.00	547.10		de ✓	547.10 ✓
11	3	U52116-47050 SUPPORT, FR BUMPER	1.00	84.70		rel ✓	84.70 ✓
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature	Charge Summary		Total		
		Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd			
			Document No. 0		3 Media Close #07-03 Singapore 138498			
			Document Date 04/04/2022		Work: 65703925			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q3	19/12/2017	SLU9532U	0	14332	66TP/SLU9532U/040422	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU003564857		2ZRS065682	60	Shashitharan	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
12	4	U53802-47100 FENDER SUB-ASSY, FR			1.00	1037.80		bt 1037.80 ✓
13	5	U52023-47030 REINFORCEMENT			1.00	353.10		bt 353.10 ✓
14	6	U52575-47040 RETAINER, RR BUMPER			1.00	124.90		de 124.90 ✓
15	7	U52159-47913 COVER, RR BUMPER			1.00	469.50		de 469.50 ✓
16	8	U52453-47010 GUARD, RR BUMPER,			1.00	611.30		de 611.30 ✓
17	9	U52565-47900 FILLER, RR BUMPER			1.00	131.10		de 131.10 ✓
18	0	S52161-0K040 PIECE, RR BUMPER			5.00	4.30		rel 21.50 ✓
19	1	U81591-47011 LENS & BODY, RR			1.00	532.00		nn X 532.00
20	2	U81561-47153 LENS & BODY, RR			1.00	469.90		nn X 469.90
<i>Tanpin 97495749/62563561</i> <i>wp 6/4/22 & 3pm</i> <i>*Resurvey before paint</i> <i>Tanpin @ Lian-to.com</i> <i>6 days</i>					LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
For & on behalf of			Customer's Signature		Acknowledged by Repairer		Total	11,627.60
Borneo Motors (Singapore) Pte Ltd					Signature: Charge Summary		11643.9	
			Date:				GST 7.00%	813.93
Please acknowledge receipt of vehicle			Parts		4,437.60		Less	0.00
			Labour		7,190.00			
			Sublet		0.00			
			Lubrication/Fluid		0.00			
			Others		0.00		Amount Due	12,441.53