



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd				
		Document No. 0	3 Media Close #07-03 Singapore 138498				
		Document Date 04/04/2022	Work: 65703925				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	19/12/2017	SLU9532U	0	14332	66TP/SLU9532U/040422
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU003564857		2ZRS065682	60	Shashitharan	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SLR4559S ACC DATE:040422 DRIVE IN:04/04/22 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50.	100.00
2	B	BP-LAB2 CHECK WIRIN GAND CONDUCT REFOCUS HEADLAM P				✓	180.00
3	B	BP-LAB2 REPL ACC AFF PARTS ANDPANEL STRAIGHTEN AND REALIGN ACC AFF AREA FRT PORTION				1080	2160.00
4	B	BP-RES2 RESRPAY ACC AFF AREA FRT PORTION				1180.	1770.00
5	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SESNOR RE AR PORTION				✓	180.00
6	B	BP-LAB2 CONDUCT LEAK TEST REST REAR PORTION				✓	180.00
7	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA REEAR PORTION				720	1440.00
8	B	BP-RES2 RESRPAY ACC AFF AREA REAR PORTION				590	1180.00
9	1	U53395-47040 SEAL, HOOD TO FR END	1.00	54.70		rel ✓	54.70
10	2	U52119-47962 COVER, FR BUMPER	1.00	547.10		de ✓	547.10
11	3	U52116-47050 SUPPORT, FR BUMPER	1.00	84.70		rel ✓	84.70
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet				
			Lubrication/Fluid		Amount Due		
			Others				

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details					
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd 3 Media Close #07-03 Singapore 138498 Work: 65703925					
		Document No. 0						
		Document Date 04/04/2022						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q3	19/12/2017	SLU9532U	0	14332	66TP/SLU9532U/040422	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDK3BFU003564857		2ZRS065682	60	Shashitharan	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
12	4	U53802-47100	FENDER SUB-ASSY, FR			1.00	1037.80	bt 1037.80
13	5	U52023-47030	REINFORCEMENT			1.00	353.10	bt 353.10
14	6	U52575-47040	RETAINER, RR BUMPER			1.00	124.90	de 124.90
15	7	U52159-47913	COVER, RR BUMPER			1.00	469.50	de 469.50
16	8	U52453-47010	GUARD, RR BUMPER,			1.00	611.30	de 611.30
17	9	U52565-47900	FILLER, RR BUMPER			1.00	131.10	de 131.10
18	0	S52161-0K040	PIECE,RR BUMPER			5.00	4.30	rec 21.50
19	1	U81591-47011	LENS & BODY, RR			1.00	532.00	? 532.00
20	2	U81561-47153	LENS & BODY, RR			1.00	469.90	? 469.90
<i>Tanpin 97495749/62563561</i> <i>wp/ 6/4/22 3pm</i> <i>*Resurvey before paint</i> <i>Tanpin @ Inlandco.com</i> <i>6 days</i> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company								
For & on behalf of		Customer's Signature			Acknowledged by Repairer		Total	
Borneo Motors (Singapore) Pte Ltd		Signature:			Charge Summary		11,627.60	
		Date:						
		Please acknowledge receipt of vehicle			Parts 4,437.60		GST 7.00% 813.93	
					Labour 7,190.00		Less 0.00	
					Sublet 0.00			
					Lubrication/Fluid 0.00			
					Others 0.00		Amount Due 12,441.53	

Company Copy