



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD  
8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN: KOH JANICE

Ref: CS/ASM22003165/Uvy3e2  
Date: 04/05/2022  
Code: ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SKL 6131Y	<b>Veh. Inspected</b>	SMG 4888M
<b>Policy No.</b>	GA603927	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S2M03XPL	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	KOH JANICE	<b>Assign Date</b>	06/04/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MERCEDES BENZ CLA180 COUPE (A)	<b>c.c</b>	1595
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
<b>Chassis No.</b>	WDD1173422N687694	<b>Colour</b>	SILVER / WHITE
<b>Odometer</b>	35821 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	225/40 R18	PIRELLI	7 mm
<b>L/H Front Tyre</b>	225/40 R18	PIRELLI	7 mm
<b>R/H Rear Tyre</b>	225/40 R18	PIRELLI	7 mm
<b>L/H Rear Tyre</b>	225/40 R18	PIRELLI	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	01/04/2022	<b>Inspection Date</b>	11/04/2022
<b>Survey held at</b>	1 Kaki Bukit Avenue 6, #01-55, Autobay S417883		
<b>Repairer</b>	BLUWEL AUTOMOTIVE SERVICE PL		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**