

Our Job Ref No : 305511402

Date : 11/04/22

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508909
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr Thovan

Vehicle Reg No. : SHB4803T

01/04/2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: EQ --- GBE5553M
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges \$0.00
 - Total for Part-By-Part Repair Cost**
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$10,200.00
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 4 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Ms. Loke YY

Tel : 62148355

Fax : 65468156

Signature : 

Name : Thovan

Date : 22/4/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 05 Apr 2022)**Parts:** 144 TOYOTA PRIUS 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHB4803T/05/04/2022 11:16**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount
1	1		*REAR BUMPER	Cut	25.00	0.00	*503.04 FL
2	1		*REAR BUMPER CLIPS	nee	25.00	0.00	*22.00 FL
3	1		*REAR BUMPER LOWER COVER	Cut	25.00	0.00	*654.96 FL
4	1		*REAR BUMPER UNDER SIDE CENTRE COVER	Cut	25.00	0.00	*654.96 FL
5	1		*COVER FLOOR UNDER NO. 2	mis	25.00	0.00	*220.50 FL
6	1		*REAR BUMPER UNDER SIDE COVER RH	Cut	25.00	0.00	*232.00 FL
7	1		*REAR BUMPER TOWING COVER	Cut	25.00	0.00	*82.70 FL
8	1		*REAR BUMPER SIDE RETAINER LH	nee	25.00	0.00	*112.70 FL
9	1		*REAR BUMPER SIDE RETAINER RH	nee	25.00	0.00	*112.70 FL
10	1		*REAR BUMPER REINFORCEMENT	PT	25.00	0.00	*378.32 FL
11	1		*REAR BUMPER ARM ASSY LH	DT	25.00	0.00	*139.60 FL
12	1		*REAR BUMPER ARM ASSY RH	DT	25.00	0.00	*139.60 FL
13	1		*REAR BUMPER SIDE EXTENTION RH	Cut	25.00	0.00	*148.40 FL
14	1		*REAR END PANEL	SVC X 1	25.00	0.00	*738.96 FL
15	1		*REAR END PANEL GARNISH	SVC X 1	25.00	0.00	*165.80 FL
16	1		*REAR WIRING ASSY	SVC X 1	25.00	0.00	*582.40 FL
17	1		*REAR SPOILER SUB ASSY	DT	25.00	0.00	*1,787.79 FL
18	1		*ROOF TOP CENTER COVER-BLACK	mis	25.00	0.00	*956.30 FL
19	1		*BACK DOOR GARNISH SUB ASSY	PT	25.00	0.00	*1,054.71 FL
20	1		*REAR TRUNK LID LOGO (PRIUS)	nee	25.00	0.00	*62.14 FL
21	1		*REAR TRUNK LID LOGO (HYBRID)	nee	25.00	0.00	*62.14 FL
22	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	nee	25.00	0.00	*81.43 FL
23	1		*TAIL LAMP UPPER RH	Cra	25.00	0.00	*557.90 FL
24	1		*TAIL LAMP LOWER RH	Cra	25.00	0.00	*570.00 FL
25	1		*REAR SPARE TYRE PANEL	1	25.00	0.00	*667.70 FL
26	1		*REAR WINDSCREEN GLASS WITH MOULDING	nee	25.00	0.00	*1,884.32 FL
27	1		*REAR TRUNK LID COVER	nee	25.00	0.00	*1,303.29 FL
28	1		*REAR TRUNK LID GLASS	nee	25.00	0.00	*1,569.70 FL
29	1		*REAR TRUNK LID HINGE LH	SVC nee X	25.00	0.00	*69.32 FL
30	1		*REAR TRUNK LID HINGE RH	SVC nee X	25.00	0.00	*69.32 FL
31	1		*REAR TRUNK LID LOCK	SVC jam	25.00	0.00	*530.79 FL
32	1		*REAR TRUNK LID COVER TRIM BOARD	SVC X 1	25.00	0.00	*254.40 FL
33	1		*BOOT LID TRIMBOARD CENTRE	SVC X 1	25.00	0.00	*159.60 FL
34	1		*BOOTLID TRIMBOARD SIDE RH	SVC X 1	25.00	0.00	*92.50 FL
35	1		*BOOT HANDLE	SVC X 1	25.00	0.00	*31.80 FL
36	1		*REAR TRUNK LID RUBBER	SVC X 1	25.00	0.00	*365.20 FL
37	1		*REAR TRUNK LID ABSORBER LH	SVC X 1	25.00	0.00	*287.50 FL
38	1		*REAR TRUNK LID ABSORBER RH	SVC X 1	25.00	0.00	*287.50 FL
39	1		*REAR TRUNK LID STOPPER LH	SVC X 1	25.00	0.00	*84.80 FL
40	1		*REAR TRUNK LID STOPPER RH	SVC X 1	25.00	0.00	*84.80 FL
41	1		*REAR EXHAUST PIPE CENTRE INSULATOR	X	25.00	0.00	*498.60 FL
42	1		*REAR EXHAUST PIPE HANGER	SVC X	25.00	0.00	*40.70 FL
43	1		*REAR EXHAUST PIPE	X	25.00	0.00	*1,163.40 FL
44	1		*REPLACE REAR FENDER ADVERTISEMENT LOGO LH	ne	0.00	0.00	*100.00 F
45	1		*REPLACE REAR FENDER ADVERTISEMENT LOGO RH	ne	0.00	0.00	*100.00 F

ComfortDelGro Engineering Pte Ltd/SHB4803T/05/04/2022 11:16. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount
46	1		*REPLACE REAR BUMPER ADVERTISEMENT LOGO	NS /	0.00	0.00	*50.00 F
47	1		*REVERSE CAMERA ASSY	SVC X /	0.00	0.00	*380.00 F
48	1		*REAR TRUNK LID COMFORT & TEL NO. STICKER	NS /	0.00	0.00	*60.00 F
49	1		*REAR TRUNK LID APPS STICKER	NS /	0.00	0.00	*40.00 F
50	1		*REAR BUMPER RUBBER MAT	NS /	0.00	0.00	*55.00 F
51	1		*REAR REVERSE SENSOR	CUR /	0.00	0.00	*135.70 F

F=Franchise part, L=ListItemDisc.

Sub Total (S\$)	20,386.99
- List Item Discount on L Items (S\$)	4,866.57
Total Parts (S\$)	15,520.42

ComfortDelGro Engineering Pte Ltd/SHB4803T/05/04/2022 11:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	700 1,900.00
2	SPRAY PAINTING CHARGE	New	750 2000 1,350.00
3	TOWING FEE - KING DOLLY	New	100 150.00
4	CHECK ALL LIGHTING	New	40 80.00
5	TUFF KOTE	New	40 80.00
6	REMOVE/ REFIX EXHAUST PIPE	New	70 150.00
7	REMOVE/ REFIX REAR WINDSCREEN GLASS	New	✓ 120.00
8	REMOVE/REFIX REVERSE SENSOR	New	30 60.00
Gross Labour Cost (\$\$)			3,890.00

ComfortDelGro Engineering Pte Ltd/SHB4803T/05/04/2022 11:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Theran

82235769

6/4/22 1645

LPS repair

4 days w/p

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: