

**ComfortDelGro Engineering Pte Ltd** (Co.Reg.No:199506048W)

 205 Braddell Road  
 Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email: teokeejin@cdge.com.sg

 INSURER: **India International Insurance Pte Ltd (HQ)**
**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D20MFL0000326_01	Date of Loss:	25/03/2022
Vehicle Reg. No.:	<b>SFH8800S</b>	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	COMFORTDELGRO RENT-A-CAR PTE LTD		
Driver:	CALVIN LOW BAO CAN		

Make/Model:	VOLVO V60, 2.0 T2 CROSS COUNTRY (A)	Vehicle Reg. Date:	16/11/2017
Vehicle Colour:	WHITE	Chassis No:	YV1FZ40LDJ2045410
Engine No:	B4204T112215713		
Odometer:	10000 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day):	6 ✓		

*Not Withain  
Meriva B4 paint*

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

COST OF CLAIMS		Amount
Parts		33,891.75
Miscellaneous Items		11.00
Labour		3,210.00
Paintwork Labour		0.00
Towing		0.00
	<b>Gross Total (S\$)</b>	<b>37,112.75</b>
	<b>+ GST 7.00% (S\$)</b>	<b>2,597.89</b>
	<b>Nett Amount (S\$)</b>	<b>39,710.64</b>

This claim is handled by: NGO TOH WEE

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**PAIR DETAILS**

Reference

<b>Part Source:</b>	(Last Synchronised: 06 Apr 2022)	
<b>Parts:</b>	N/A	VOLVO V60 2.0 T2 CROSS COUNTRY (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFH8800S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*DRIVER AIRBAG	10.00	0.00	*2,550.00 FL	✓
2	1		*DRIVER CLOCK SPRING	10.00	0.00	*450.00 FL	✓
3	1		*DRIVER SEAT BELT	10.00	0.00	*1,260.00 FL	✓
4	1		*DRIVER SEAT BELT BUCKLE	10.00	0.00	*420.00 FL	✓
5	1		*PASSENGER AIRBAG	10.00	0.00	*3,600.00 FL	✓
6	1		*PASSENGER SEAT BELT	10.00	0.00	*1,260.00 FL	✓
7	1		*PASSENGER SEAT BELT BUCKLE	10.00	0.00	*420.00 FL	✓
8	1		*AIRBAG CONTROL UNIT	10.00	0.00	*2,850.00 FL	✓
9	1		*LH ROOF CURTAIN AIRBAG	10.00	0.00	*2,175.00 FL	✓
10	1		*RH ROOF CURTAIN AIRBAG	10.00	0.00	*2,175.00 FL	✓
11	1		*ROOF LINING	10.00	0.00	*2,700.00 FL	✓
12	1		*DASH BOARD	10.00	0.00	*5,775.00 FL	✓
13	1		*LH FRT FENDER	10.00	0.00	*870.00 FL	✓
14	1		*LH FRT FENDER ARCH GARNISH	10.00	0.00	*630.00 FL	✓
15	1		*LH FRT FENDER INNER SHIELD	10.00	0.00	*442.50 FL	✓
16	10		*LH FRT FENDER INNER SHIELD CLIPS	10.00	0.00	*55.00 FL	✓
17	1		*LH ROCKER PANEL GARNISH	10.00	0.00	*510.00 FL	✓
18	1		*FRT BUMPER	10.00	0.00	*1,650.00 FL	✓
19	1		*FRT BUMPER SIDE RETAINER LH	10.00	0.00	*105.00 FL	✓
20	1		*FRT BUMPER SIDE RETAINER RH	10.00	0.00	*105.00 FL	✓
21	1		*LH FRT LOWER ARM	10.00	0.00	*375.00 FL	✓
22	1		*LH FRT KUNCKLE ARM	10.00	0.00	*1,050.00 FL	✓
23	1		*LH FRT KUNCKLE BEARING	10.00	0.00	*510.00 FL	✓
24	1		*LH FRT SHOCK ABSORBER	10.00	0.00	*360.00 FL	✓
25	1		*LH FRT RIM R18	10.00	0.00	*1,800.00 FL	✓
26	1		*LH FRT TYRE 235/50ZR 18 DAVANTI DX640	0	0.00	*420.00 FS	✓
27	1		*LH REAR TYRE 235/50ZR 18 DAVANTI DX640	0	0.00	*420.00 FS	✓
28	1		*FRT WINDSCREEN GLASS	10.00	0.00	*1,200.00 FL	✓
29	1		*LH REAR FENDER ARCH GARNISH	10.00	0.00	*600.00 FL	✓
30	1		*LH B PILLAR INNER TOP TRIM	10.00	0.00	*360.00 FL	✓
31	1		*RH B PILLAR INNER TOP TRIM	10.00	0.00	*360.00 FL	✓
32	1		*SEALANT	0	0.00	*40.00 FS	✓
33	1		*INNER SEAL	0	0.00	*30.00 FS	✓
34	1		*ERP BRACKET	0	0.00	*26.00 FS	✓

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>37,553.50</b>
<b>- List Item Discount on L Items (\$\$)</b>	<b>3,661.75</b>
<b>Total Parts (\$\$)</b>	<b>33,891.75</b>

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

### Estimates on Miscellaneous Items

Qty	Particulars	Amount
<b>Miscellaneous Items</b>		
1	1 OD/TP Case (Insurer)	11.00
<b>Sub Total (S\$)</b>		<b>11.00</b>

### Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO REMOVE AND INSTALL FRT WINDSCREEN GLASS	New	120.00
2	TO KNOCK, STRAIGHTEN AND RENEW ACCIDENT AREA SUCH AS FRT BUMPER, LH FRT FENDER, LH FRT DOOR, LH SIDE ROCKER PANEL GARNISH, LH REAR FENDER AND ETC	New	540 720.00
3	TO PUTTY AND RESRPAY ACCIDENT AREA SUCH AS FRT BUMPER, LH FRT FENDER, LH FRT DOOR, LH SIDE ROCKER PANEL GARNISH, LH REAR FENDER AND ETC	New	750 1,300.00
4	TO RESET AND PROGRAM AIRBAG SYSTEM	New	250.00
5	TO REMOVE AND INSTALL DRIVER AIRBAG, PASSENGER AIRBAG, ALL SEAT BELT AND CONTROL UNIT	New	250.00
6	TO REMOVE AND INSTALL DASH BORAD	New	250.00
7	TO REMOVE AND INSTALL LH FRT UNDER CARRIAGE	New	240.00
8	TO CONDUCT WHEEL ALGINMENT	New	80.00
<b>Gross Labour Cost (S\$)</b>			<b>3,210.00</b>

Report was unsubmitted during this print-out.  
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >