



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|--|---|------------|
| ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897 | | | Ref: CS/AIS22003176/Evy3n2 Date: 03/06/2022 Code: AIS | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SKM 1569X | Veh. Inspected | SGR 5129C |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | 2022 22004406/SL | Excess (\$) | 0.00 |
| | Assign From | SHANTI | Assign Date | 06/04/2022 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | TOYOTA VIOS | c.c | 1496 |
| | Engine No. | HIDDEN | Year of Reg. | 2018 |
| | Chassis No. | MR2B23F3901154215 | Colour | SILVER |
| | Odometer | 27005 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 185/60 R15 | DUNLOP | 4 mm |
| | L/H Front Tyre | 185/60 R15 | DUNLOP | 4 mm |
| | R/H Rear Tyre | 185/60 R15 | DUNLOP | 4 mm |
| | L/H Rear Tyre | 185/60 R15 | DUNLOP | 4 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 30/03/2022 | Inspection Date | 17/05/2022 |
| | Survey held at | BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462 | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 5 Working Days | |