



Wicked Works Garage Pte Ltd

Wicked Works Garage Pte Ltd
 (Solely for the purpose of providing repair services)
 confirmation
 "Without Prejudice" basis
 is allowed
 must be resurveyed and
 from Insurance Company

Blk 13 Kaki Bukit Road 4
 #01-04 Bartley Biz Centre Singapore 417807
 general.wickedworks@gmail.com
 HP : 9004 0057

ACKNOWLEDGED BY REPAIRER

Signature:

Date:

Not Authorized WP
 4/5 \$1300
 3 days
 6/4/22

6 April 2022

REG NO. : SME 874 P
 MAKE/MODEL : KIA CERATO FORTE

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
LIST ITEMS		
1	Rear boot lid 11	\$ 793.80 X
2	Rear boot hinges 11	\$ 250.00 X
2	Rear boot lamps 11	\$ 373.00 X
1	Rear boot inner lock 11	\$ 126.50 X
1	Rear boot rubber 11	\$ 128.60 X
1	Rear boot "KIA" emblem 11	\$ 52.50 X
2	Rear taillamps 11	\$ 975.20 X
1	Rear end panel 11	\$ 598.50 X
1	Rear end panel inner garnish 11	\$ 152.50 X
1	Rear smart keyless sensor 11	\$ 185.50 X
1	Rear bumper De	\$ 658.00 ✓
1	Rear bumper inner sponge 11	\$ 145.50 X
1	Rear bumper reinforcement 11	\$ 356.00 X
2	Rear bumper reinforcement stays 11	\$ 305.00 X
3	Rear bumper reinforcement brackets 11	\$ 68.70 X
2	Rear bumper side retainers 11	\$ 77.00 X
2	Rear bumper PDC sensors Day	\$ 373.00 200 S/N
		\$ 5,619.30
	Less 10%	\$ 561.93
		\$ 5,057.37

SPECIAL NETT ITEMS

1	Rear bumper clip (1 set) 11	\$ 50.00 ✓
1	Rear bumper lower spoiler R	\$ 750.00 X
		\$ 800.00

S/N LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 20
2	To remove and refit inner garnishes.	\$ 11 150.00 X
3	To remove and refit rear reverse sensor.	\$ 150.00 50
4	To transfer boot lid mechanism and wiring assembly.	\$ 11 80.00 X
5	To apply undercoating.	\$ 11 200.00 X
6	Panel beating.	\$ 1,500.00 300
7	To re-spray painting on the affected areas.	\$ 1,400.00 450
		\$ 3,560.00

GRAND TOTAL :

\$ 9,417.37
 2-658
 102
 2-592.20
 S.N-250
 2-820
 1662.2
 1328