

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/04/2022


User ID : TuckFoo

Section A - Accident Details

Registration Number	SHF365X
Case Reference Number	TAX/04/22/2012
Registration Date	12/19/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LIM MUI LANG
Type of Accident	Others
Accident Date and Time	4/4/2022 5:15 PM
Accident Reported Date and Time	4/5/2022 10:57 AM
Insurance Surveyor Required?	Yes
Surveyed by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24114473
Special Instruction to ARC, if any	TP / FRONT PORTION/TOWED \$40
Prepared Date and Time	4/5/2022 1:04 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$0.00 500
Total Spray Cost	\$1,314.00	\$0.00 600
Total Spare Part Cost	\$19,531.69	\$0.00 *
Total Other Cost	\$696.00	\$0.00 *
TOTAL COST	\$22,555.69	\$0.00
ump Sum Total	\$22,550.00	\$0.00
Number of Repair Days	10.0	5 days + 2 = 7 days
Prepared / Adjusted By	Boon Chew Tay	Rasul
ARC / Surveyor Sign Off Date	05/04/2022 1:55 PM	
Signature		 4/5 Rasul 06/04/22 @ 1555 hrs
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 69662623
Accident Reporting Number : 68662672

Date Generated : 06/04/2022

User ID : TuckFoo

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5341047130	HINGE ASSY, HOOD, RH	1.00	\$57.00	25.00	\$42.75	Replace	X AN
		5330147110	HOOD SUB-ASSY	1.00	\$938.40	25.00	\$703.80	Replace	regr
		8101647090	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	1.00	\$486.40	10.00	\$437.76	Replace	? X AN
		8105647090	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1.00	\$486.40	10.00	\$437.76	Replace	X AN
		8114547091	UNIT, HEADLAMP, RH	1.00	\$2,558.00	10.00	\$2,303.01	Replace	GA
		8118547091	UNIT, HEADLAMP, LH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	X AN
		8122047020	LAMP ASSY, FOG, LH	1.00	\$910.20	10.00	\$819.18	Replace	X AN
		5210347010	EXTENSION SUB-ASSY, LH	1.00	\$116.30	25.00	\$87.23	Replace	X AN
		5210247020	EXTENSION SUB-ASSY, RH	1.00	\$116.30	25.00	\$87.23	Replace	? X AN
		5213247010	REINFORCEMENT FRONT LOWER	1.00	\$238.50	25.00	\$178.88	Replace	X AN
		5261847090	ABSORBER, FR BUMPER LOWER	1.00	\$117.00	25.00	\$87.75	Replace	X AN
		5339547040	SEAL, HOOD TO FR END	1.00	\$24.40	25.00	\$18.30	Replace	X AN
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	na
		5144747030	COVER, ENGINE UNDER CENTER	1.00	\$94.50	25.00	\$70.88	Replace	? X AN
		5144347020	COVER, ENGINE UNDER SIDE RH	1.00	\$76.90	25.00	\$57.68	Replace	? X AN
		5144447010	COVER, ENGINE UNDER SIDE LH	1.00	\$76.90	25.00	\$57.68	Replace	X AN
		5144247030	COVER, ENGINE UNDER, REAR	1.00	\$36.50	25.00	\$27.38	Replace	X AN
		8121047020	LAMP ASSY, FOG, RH	1.00	\$910.20	10.00	\$819.18	Replace	X AN
		5211547050	SUPPORT, FR BUMPER RH	1.00	\$78.90	25.00	\$57.68	Replace	? X AN
		5211647050	SUPPORT, FR BUMPER LH	1.00	\$82.30	25.00	\$61.72	Replace	X AN
		5212747907	COVER, FR BUMPER RH	1.00	\$28.10	25.00	\$21.08	Replace	X AN
		5212847906	COVER, FR BUMPER LH	1.00	\$28.10	25.00	\$21.08	Replace	X AN
		5211447190	BRACKET, FR BUMPER	1.00	\$99.80	25.00	\$74.85	Replace	X AN
		5321747030	BRACE, HOOD LOCK SUPPORT	1.00	\$76.20	25.00	\$57.15	Replace	X AN
		5110847020	FRONT REINFORCEMENT SIDE LH	1.00	\$129.30	25.00	\$96.98	Replace	X AN
		5302847010	SUPPORT SUB-ASSY LOWER	1.00	\$397.40	25.00	\$298.05	Replace	? X AN
		8531947170	WIPER WASHER INLET	1.00	\$55.40	25.00	\$41.55	Replace	X AN
		85330-8010	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	1.00	\$245.00	10.00	\$220.50	Replace	X AN
		1659237020	GUIDE, RADIATOR AIR,	1.00	\$93.90	25.00	\$70.43	Replace	X AN
		5315547010	SEAL, RADIATOR GRILLE	2.00	\$40.70	25.00	\$61.05	Replace	? X AN
		1640037310	RADIATOR ASSY	1.00	\$1,841.10	25.00	\$1,380.82	Replace	X AN
		1636137070	FAN RADIATOR, RH	1.00	\$233.00	25.00	\$174.75	Replace	X AN
		1636137060	FAN RADIATOR, LH	1.00	\$181.80	25.00	\$136.35	Replace	X AN
		1671137160	FAN SHROUD RADIATOR	1.00	\$219.30	25.00	\$164.48	Replace	X AN
		1636336160	MOTOR, COOLING FAN, RH	1.00	\$443.40	10.00	\$399.06	Replace	X AN
		1636337060	MOTOR, COOLING FAN, LH	1.00	\$543.50	10.00	\$489.15	Replace	X AN
		8846010320	AIR CON CONDENSER ASSY	1.00	\$1,317.70	25.00	\$988.28	Replace	X AN

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/04/2022

User ID : TuckFoo

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		8211147J21	WIRE, ENGINE ROOM MAIN	1.00	\$6,138.00	10.00	\$5,524.20	Replace	Xan
		821H247010	WIRE, AIR CONDITIONER	1.00	\$445.70	10.00	\$401.13	Replace	Xan
		5360147080	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	25.00	\$699.83	Replace	bt
		7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	nu
		5387547070	LINER, FR FENDER, RH	1.00	\$198.40	25.00	\$148.80	Replace	cut
		5385147061	PAD, FR WHEEL RH	1.00	\$57.70	25.00	\$43.28	Replace	nu
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	scr
		5261147140	ABSORBER, FR BUMPER	1.00	\$70.30	25.00	\$52.72	Replace	ca
		7531047060	EMBLEM ASSY FRONT	1.00	\$87.10	25.00	\$65.32	Replace	ca
		5310147080	GRILLE SUB-ASSY	1.00	\$335.60	25.00	\$251.70	Replace	de
		5142047030	COVER ASSY, ENGINE	1.00	\$180.10	25.00	\$135.08	Replace	? Xan
		5141047020	COVER ASSY, ENGINE UNDER CENTER SET	1.00	\$452.80	25.00	\$339.60	Replace	? Xan
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	by side
		5311247240	GRILLE, RADIATOR	1.00	\$165.00	25.00	\$123.75	Replace	? ca
		5211947962	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	turn
total					\$29,281.10		\$24,414.61		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
total									