

Section A - Accident Details

Registration Number	SHF365X
Case Reference Number	TAX/04/22/2012
Registration Date	19/12/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LIM MUI LANG
Type of Accident	Others
Accident Date and Time	4/4/2022 5:15 PM
Accident Reported Date and Time	5/4/2022 10:57 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24114473
Special Instruction to ARC, if any	TP / FRONT PORTION/TOWED \$40
Prepared Date and Time	5/4/2022 1:04 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,214.00	\$600.00
Total Spray Cost	\$1,514.00	\$700.00
Total Spare Part Cost	\$21,165.05	\$5,774.50
Total Other Cost	\$696.00	\$80.00
TOTAL COST	\$24,589.05	\$7,154.50
Lump Sum Total	\$24,600.00	\$7,150.00 (L/S)
Number of Repair Days	10.0	7.0
Prepared / Adjusted By	Boon Chew Tay	Rasul (LKK) / Allianz Insurance
ARC / Surveyor Sign Off Date	19/04/2022 2:50 PM	19/04/2022 11:02 AM
Signature		
Remarks	Total number of repair days = 7 days. SUP = + 2 days Delay for Our VACS system Surveyor Portal Login page error due to	LUMP SUM REPAIR / AFTER PAINT PHOTO / TOWING CHARGE PROVIDE TOWING RECEIPT /

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2204-0407	Invoice Number	
Quotation Date	29.04.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT SUPPORT PANEL	\$200.00	\$100.00
TO REPAIR FRONT PORTION	\$1,014.00	\$500.00
Total Labour	\$1,214.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT SUPPORT PANEL	\$200.00	\$100.00
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,514.00	\$700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$120.00	\$40.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$40.00
TO TOP UP A/C GAS	\$120.00	\$0.00
TO CONDUCT RADIATOR PRESSURE CHECK	\$120.00	\$0.00
Total Other Costs	\$696.00	\$80.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace	√
		52115470 50	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Check	X
		52116470 50	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given	X
		52127479 07	COVER, FR BUMPER RH	1.00	\$28.10	25.00	\$21.08	Replace	Replace	√
		52128479 06	COVER, FR BUMPER LH	1.00	\$28.10	25.00	\$21.08	Replace	Replace	√
		52114471 90	BRACKET, FR BUMPER	0.00	\$99.80	0.00	\$0.00	Replace	Check	X
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace	√
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace	√
		52021471 10	REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Not Given	X
		52611471 40	ABSORBER, FR BUMPER	1.00	\$70.30	25.00	\$52.73	Replace	Replace	√
		52103470 10	EXTENSION SUB-ASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given	X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/05/2022

User ID PohSuan

	52102470 20	EXTENSION SUB-ASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Check	X
	52132470 10	REINFORCEMENT FRONT LOWER	0.00	\$238.50	0.00	\$0.00	Replace	Not Given	X
	52618470 90	ABSORBER, FR BUMPER LOWER	0.00	\$117.00	0.00	\$0.00	Replace	Not Given	X
	53395470 40	SEAL, HOOD TO FR END	0.00	\$24.40	0.00	\$0.00	Replace	Not Given	X
	75310470 60	EMBLEM ASSY FRONT	1.00	\$87.10	25.00	\$65.33	Replace	Replace	√
	53112472 40	GRILLE, RADIATOR	1.00	\$165.00	25.00	\$123.75	Replace	Replace	√
	53101470 80	GRILLE SUB-ASSY	1.00	\$335.60	25.00	\$251.70	Replace	Replace	√
	52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	√
	52535500 60	RETAINER, FR BUMPER, LH & RH	1.00	\$8.50	25.00	\$6.38	Replace	Replace	√
	51420470 30	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Check	X
	51410470 20	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$452.80	0.00	\$0.00	Replace	Check	X
	51447470 30	COVER, ENGINE UNDER CENTER	0.00	\$94.50	0.00	\$0.00	Replace	Check	X
	51443470 20	COVER, ENGINE UNDER SIDE RH	0.00	\$76.90	0.00	\$0.00	Replace	Check	X
	51444470 10	COVER, ENGINE UNDER SIDE LH	0.00	\$76.90	0.00	\$0.00	Replace	Not Given	X
	51442470 30	COVER, ENGINE UNDER, REAR	0.00	\$36.50	0.00	\$0.00	Replace	Not Given	X
	81210470 20	LAMP ASSY, FOG, RH	1.00	\$910.20	10.00	\$819.18	Replace	Replace	√
	81220470 20	LAMP ASSY, FOG, LH	0.00	\$910.20	0.00	\$0.00	Replace	Check	X
	81185476 91	UNIT , HEADLAMP , LH	0.00	\$2,558.90	0.00	\$0.00	Replace	Not Given	X
	81145476 91	UNIT , HEADLAMP , RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	√
	81056476 90	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Not Given	X
	81016476 90	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check	X
	53301471 10	HOOD SUB-ASSY	1.00	\$938.40	100.00	\$0.00	Replace	Repair	R
	53410471 30	HINGE ASSY, HOOD, RH	0.00	\$57.00	0.00	\$0.00	Replace	Not Given	X
	53420471 30	HINGE ASSY, HOOD, LH	0.00	\$57.00	0.00	\$0.00	Replace	Not Given	X
	53440470 60	SUPPORT ASSY, HOOD	0.00	\$41.80	0.00	\$0.00	Replace	Not Given	X
	53601520 10C1	LEVER SUB-ASSY, HOOD	0.00	\$72.60	0.00	\$0.00	Replace	Not Given	X
	53577330 10	BOLT, HOOD LOCK	0.00	\$10.00	0.00	\$0.00	Replace	Not Given	X
	53510471 40	LOCK ASSY, HOOD	0.00	\$131.10	0.00	\$0.00	Replace	Not Given	X
	53217470 30	BRACE, HOOD LOCK SUPPORT	0.00	\$76.20	0.00	\$0.00	Replace	Not Given	X
	51107470 20	FRONT REINFORCEMENT SIDE RH	0.00	\$128.20	0.00	\$0.00	Replace	Check	X
	51108470 20	FRONT REINFORCEMENT SIDE LH	0.00	\$129.30	0.00	\$0.00	Replace	Not Given	X
	51228470 10	FRONT PLATE, FR SUSPENSION	0.00	\$9.40	0.00	\$0.00	Replace	Not Given	X
	53205479 00	SUPPORT S/A UPPER,	0.00	\$364.90	0.00	\$0.00	Replace	Check	X
	53202479 01	SUPPORT S/A RH	0.00	\$237.00	0.00	\$0.00	Replace	Check	X
	53203479 01	SUPPORT S/A LH	0.00	\$237.00	0.00	\$0.00	Replace	Check	X
	53028470 10	SUPPORT SUB-ASSY LOWER	0.00	\$397.40	0.00	\$0.00	Replace	Check	X
	53213470 50	SUPPORT, RADIATOR UPPER RH	0.00	\$76.70	0.00	\$0.00	Replace	Check	X
	53214470 50	SUPPORT, RADIATOR UPPER LH	0.00	\$76.70	0.00	\$0.00	Replace	Not Given	X
	85319471 70	WIPER WASHER INLET	0.00	\$55.40	0.00	\$0.00	Replace	Not Given	X
	85315471 60	WIPER WASHER JAR	1.00	\$183.60	25.00	\$137.70	Replace	Replace	√
	85330-58010	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	0.00	\$245.00	0.00	\$0.00	Replace	Not Given	X
	16592370 20	GUIDE, RADIATOR AIR,	0.00	\$93.90	0.00	\$0.00	Replace	Not Given	X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/05/2022

User ID : PohSuan

	53155470 10	SEAL, RADIATOR GRILLE	0.00	\$40.70	0.00	\$0.00	Replace	Check	X
	16400373 10	RADIATOR ASSY	0.00	\$1,841.10	0.00	\$0.00	Replace	Not Given	X
	16361370 70	FAN RADIATOR , RH	0.00	\$233.00	0.00	\$0.00	Replace	Not Given	X
	16361370 60	FAN RADIATOR , LH	0.00	\$181.80	0.00	\$0.00	Replace	Not Given	X
	16711371 60	FAN SHROUD RADIATOR	0.00	\$219.30	0.00	\$0.00	Replace	Not Given	X
	16363361 60	MOTOR, COOLING FAN , RH	0.00	\$443.40	0.00	\$0.00	Replace	Not Given	X
	16363370 60	MOTOR, COOLING FAN , LH	0.00	\$543.50	0.00	\$0.00	Replace	Not Given	X
	88460103 20	AIR CON CONDENSER ASSY	0.00	\$1,317.70	0.00	\$0.00	Replace	Not Given	X
	8211147J 21	WIRE, ENGINE ROOM MAIN	0.00	\$6,138.00	0.00	\$0.00	Replace	Not Given	X
	82123470 60	WIRE, ENGINE, NO.3	0.00	\$260.40	0.00	\$0.00	Replace	Check	X
	821H2470 10	WIRE, AIR CONDITIONER	0.00	\$445.70	0.00	\$0.00	Replace	Not Given	X
	53801470 80	FENDER SUB-ASSY, FR , RH	1.00	\$933.10	25.00	\$699.83	Replace	Replace	√
	75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace	√
	53875470 70	LINER, FR FENDER, RH	1.00	\$198.40	25.00	\$148.80	Replace	Replace	√
	53851470 61	PAD, FR WHEEL RH	1.00	\$57.70	25.00	\$43.28	Replace	Replace	√
	53807470 20	SEAL SUB-ASSY, RH	0.00	\$50.20	0.00	\$0.00	Replace	Check	X
	53827470 50	PROTECTOR, FR FENDER RH	0.00	\$90.40	0.00	\$0.00	Replace	Check	X
	53701471 11	APRON SUB-ASSY, FRONT FENDER , RH	0.00	\$944.20	0.00	\$0.00	Replace	Check	X
Total				\$29,281.10		\$5,176.41			

Added Spare Parts / Material Usage After Surveyor Signed off										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		52115470 50	SUPPORT, FR BUMPER RH	1.00	\$76.90	25.00	\$57.68	Replace	Replace	√ mis
		52618470 90	ABSORBER, FR BUMPER LOWER	1.00	\$117.00	25.00	\$87.75	Replace	Replace	√ de
		51420470 30	COVER ASSY, ENGINE	1.00	\$180.10	25.00	\$135.08	Replace	Replace	√ cra
		51410470 20	COVER ASSY, ENGINE UNDER CENTER SET	1.00	\$452.80	25.00	\$339.60	Replace	Replace	√ cra
		51443470 20	COVER, ENGINE UNDER SIDE RH	1.00	\$76.90	25.00	\$57.68	Replace	Replace	√ cra
		51444470 10	COVER, ENGINE UNDER SIDE LH	1.00	\$76.90	25.00	\$57.68	Replace	Replace	√ cra
		81220470 20	LAMP ASSY, FOG, LH	1.00	\$910.20	10.00	\$819.18	Replace	Replace	√ cra
		53028470 10	SUPPORT SUB-ASSY LOWER	1.00	\$397.40	25.00	\$298.05	Replace	Replace	√ bt
		53876471 10	LINER, FR FENDER, LH	1.00	\$194.30	25.00	\$145.73	Replace	Replace	√ cut
		53852470 41	PAD, FR WHEEL LH	1.00	\$57.70	25.00	\$43.28	Replace	Replace	√ cut
Total					2,540.20		2,041.71			

	7,218.12	
	-20%	
	<u>5774.50</u>	
+	600.00	L/S \$7,150/-
+	<u>780.00</u>	
	<u>7,154.50</u>	