

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22003182/Uvy3n2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHC 239924		Date	± 29/04/2022	
			Code	e: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJS 9248A	Veh. Inspected	GBA 1118J	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10014490/KY	Excess (\$)	0.00	
	Assign From	SHAFAWATI MD RABU	Assign Date	06/04/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE (M)	c.c	2982	
	Engine No.	HIDDEN	Year of Reg.	2020	
	Chassis No.	JTFHT02P209990303	Colour	SILVER	
	Odometer	65309 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195 R15	OHTSU	6 mm	
	L/H Front Tyre	195 R15	OHTSU	6 mm	
	R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
	L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	28/03/2022	Inspection Date	08/04/2022	
	Survey held at	Survey held at SHIN AUTOMOBILE & TRADING PTE LTD			
		15 KAKI BUKIT ROAD 4 #01-46 BARTLEY BIZ CENTRE SINGAPORE 417808			
5a.	<del>_</del>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: