

OPTIMA WERKZ

SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg

/OptimaWerkz

/OptimaWerkz

Date: 05/04/2022

Vehicle No: SLV21115

Model: HONDA VEZEL HYBRID 1.5X

Chassis: RU31257041-2017

Reg. Year: 2017

Third Party Insurer: AIG

Third Party Veh No: SML3812L

Date of Accident: 05/04/2022

Estimator:

Surveyor:

TING AN

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE <i>953</i>	1		<i>R</i> \$972.40
2	REAR TAILGATE "VEZEL" EMBLEM	1		<i>in</i> \$58.30
3	REAR TAILGATE "HYBRID" EMBLEM	1		<i>in</i> \$75.50
4	REAR TAILGATE INNER TRIM BOARD	1		<i>mgm</i> \$203.50
5	REAR TAILGATE INNER LOCK	1		<i>in</i> \$106.40
6	REAR TAILGATE WEATHERSTRIP	1	<i>52.60m</i>	<i>dist</i> \$105.20
7	REAR TAILGATE OUTER GARNISH COVER	1		<i>mg di</i> \$189.30
8	REAR WINDSCREEN MOULDING	1		<i>in</i> \$138.60
9	REAR TAILGATE LAMP LH	1		<i>CM</i> \$480.80
10	REAR TAILGATE LAMP RH	1		<i>in</i> CM \$480.80
11	REAR TAIL LAMP LH	1		<i>CM</i> \$486.70
12	REAR TAIL LAMP RH	1		<i>CM</i> \$486.70
13	REAR BUMPER <i>762.70</i>	1		<i>BU</i> \$829.60
14	REAR BUMPER SIDE BRACKET LH	1		<i>in</i> \$37.50
15	REAR BUMPER SIDE BRACKET RH	1		<i>in</i> \$37.50
16	REAR BUMPER SMART BUZZER	1		<i>CM</i> \$110.10
17	REAR BUMPER REFELCTOR LH	1		<i>in</i> \$78.50
18	REAR BUMPER REFLECTOR RH	1		<i>in</i> \$78.50
19	REAR SIDE BUMPER LH	1		<i>in</i> \$148.50
20	REAR SIDE BUMPER RH	1		<i>in</i> \$148.50
21	REAR END PANEL	1		<i>in</i> \$452.40
22	REAR END PANEL UPPER COVER	1		<i>mg di</i> \$113.60
23	REAR FLOOR PANEL TOOLBOX TRAY	1		<i>mgm</i> \$236.10
24	REAR FLOOR PANEL TOOLBOX TRAY UPPER BOARD	1		<i>in</i> \$459.90
25	FRONT BUMPER <i>762.70</i>	1		<i>CM</i> \$817.80
26	FRONT BUMPER SIDE BRACKET LH	1		<i>DI</i> \$33.90
27	FRONT BUMPER SIDE BRACKET RH	1		<i>DI</i> \$33.90
28	FRONT GRILLE BASE	1		<i>CM</i> \$281.40
29	FRONT GRILLE OUTER CHROME MOULDING	1		<i>in</i> \$342.60
SUB TOTAL				\$8,024.50
LESS 20%				-\$1,604.90
PARTS TOTAL				\$6,419.60

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

9A Serangoon North
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

OPTIMA WERKZ SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg

/OptimaWerkz

/OptimaWerkz

Date: 05/04/2022
Vehicle No: SLV2111S
Model: HONDA VEZEL HYBRID 1.5X
Chassis: RU31257041-2017
Reg.Year: 2017

Third Party Insurer: AIG
Third Party Veh No: SML3812L
Date of Accident: 05/04/2022
Estimator: TING AN
Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		RM \$80.00
2	REAR TAILGATE INNER TRIM BOARD CLIPS	1		RM \$50.00
3	REAR BUMPER CLIPS	1		RM \$50.00
4	REAR BUMPER REVERSE SENSOR	1		RM \$300.00
5	REAR END PANEL UPPER COVER CLIPS	1		RM \$40.00
6	REAR END PANEL JOINT SEALANT	1		RM \$80.00
7	BICYCLE RACK	1	NA	Dis / Tn \$370.00
8	FRONT BUMPER CLIPS	1		RM \$50.00
S/N TOTAL				\$1,020.00

Claim Separately

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

\$1,400.00 1200

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR SIDE BUMPER LH, REAR SIDE BUMPER RH, REAR END PANEL, FRONT BUMPER & ETC.

1100
\$1,400.00

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN MOULDING & ETC. TO EFFECT REPLACE OF REAR TAILGATE.

\$150.00 120

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

\$120.00 60

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$100.00 50

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$150.00 90

TO CHECK WIRING & CENTRAL LOCKING SYSTEM.

\$80.00 30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LABOUR TOTAL \$3,400.00

TOTAL \$10,839.60

TING AN

Acknowledged by Repairer

Signature:

Branch (Motor Insurance Claims)

Date: 05/04/2022
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554800
Tel: (+65) 6484 9910 | Fax: (+65) 6481 1993

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554800
Tel: (+65) 6484 9910 | Fax: (+65) 6481 1993

Date: 11/04/2022
Vehicle No: SLV2111S
Model: HONDA VEZEL HYBRID 1.5X
Chassis: RU31257041-2017
Reg. Year: 2017

Third Party Insurer: AIG
Third Party Veh No: SML3812L
Date of Accident: 05/04/2022

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR FLOOR PANEL	1		1711.36 \$939.20
SUB TOTAL				\$939.20
LESS 20%				-\$187.84
PARTS TOTAL				\$751.36

SUPPLEMENTARY

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE & READJUST REAR FLOOR PANEL & ETC.

RM \$300.00 X

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR FLOOR PANEL & ETC.

RM \$300.00 X

LABOUR TOTAL \$600.00

TING AN

TOTAL \$1,351.36

Head office

8 Kung Chong Road Singapore 150143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1903

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Resurvey No. of Trlp:

Survey Fee:

Transportation

☐ Site Insp (\$

) \$ + RS. SI

☐ Interview (\$

) Fee