

Date: 05/04/2022

Vehicle No: SLV2111S

Model: HONDA VEZEL HYBRID 1.5X

Chassis: RU31257041-2017

Reg. Year: 2017

Third Party Insurer: AIG

Third Party Veh No: SML3812L

Date of Accident: 05/04/2022

Estimator: TING AN

Surveyor:

*Not withair
11 Day 8*

Recovery After Claim

6-7 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>R</i> \$972.40 ✓
2	REAR TAILGATE "VEZEL" EMBLEM	1		<i>h</i> \$58.30 ✓
3	REAR TAILGATE "HYBRID" EMBLEM	1		<i>h</i> \$75.50 ✓
4	REAR TAILGATE INNER TRIM BOARD	1		\$203.50 ?
5	REAR TAILGATE INNER LOCK	1		<i>h</i> \$106.40 ✓
6	REAR TAILGATE WEATHERSTRIP	1		\$105.20 ?
7	REAR TAILGATE OUTER GARNISH COVER	1		\$189.30 ?
8	REAR WINDSCREEN MOULDING	1		<i>h</i> \$138.60 ✓
9	REAR TAILGATE LAMP LH	1		<i>CM</i> \$480.80 ?
10	REAR TAILGATE LAMP RH	1		<i>CM</i> \$480.80 ✓
11	REAR TAIL LAMP LH	1		<i>CM</i> \$486.70 ✓
12	REAR TAIL LAMP RH	1		<i>CM</i> \$486.70 ✓
13	REAR BUMPER	1		<i>Bu</i> \$829.60 ✓
14	REAR BUMPER SIDE BRACKET LH	1		<i>SL</i> \$37.50 X
15	REAR BUMPER SIDE BRACKET RH	1		<i>SL</i> \$37.50 X
16	REAR BUMPER SMART BUZZER	1		\$110.10 ?
17	REAR BUMPER REFELCTOR LH	1		<i>SL</i> \$78.50 X
18	REAR BUMPER REFLECTOR RH	1		<i>SL</i> \$78.50 X
19	REAR SIDE BUMPER LH	1		<i>SL</i> \$148.50 X
20	REAR SIDE BUMPER RH	1		\$148.50 ?
21	REAR END PANEL	1		\$452.40 ?
22	REAR END PANEL UPPER COVER	1		\$113.60 ?
23	REAR FLOOR PANEL TOOLBOX TRAY	1		\$236.10 ?
24	REAR FLOOR PANEL TOOLBOX TRAY UPPER BOARD	1		\$459.90 ?
25	FRONT BUMPER	1		<i>CM</i> \$817.80 ✓
26	FRONT BUMPER SIDE BRACKET LH	1		<i>Dir</i> \$33.90 ✓
27	FRONT BUMPER SIDE BRACKET RH	1		<i>Dir</i> \$33.90 ✓
28	FRONT GRILLE BASE	1		\$281.40 ?
29	FRONT GRILLE OUTER CHROME MOULDING	1		\$342.60 ?
SUB TOTAL				\$8,024.50
LESS 20%				-\$1,604.90
PARTS TOTAL				\$6,419.60

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 05/04/2022
Vehicle No: SLV2111S
Model: HONDA VEZEL HYBRID 1.5X
Chassis: RU31257041-2017
Reg.Year: 2017

Third Party Insurer: AIG
Third Party Veh No: SML3812L
Date of Accident: 05/04/2022
Estimator: TING AN
Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>me</i> \$80.00
2	REAR TAILGATE INNER TRIM BOARD CLIPS	1		<i>me</i> \$50.00
3	REAR BUMPER CLIPS	1		<i>me</i> \$50.00
4	REAR BUMPER REVERSE SENSOR	1		<i>CRA</i> \$300.00
5	REAR END PANEL UPPER COVER CLIPS	1		\$40.00
6	REAR END PANEL JOINT SEALANT	1		\$80.00
7	BICYCLE RACK <i>P.1</i>	1		<i>Dis / Tu</i> \$370.00
8	FRONT BUMPER CLIPS	1		<i>me</i> \$50.00
S/N TOTAL				\$1,020.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

\$1,400.00 *7*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR SIDE BUMPER LH, REAR SIDE BUMPER RH, REAR END PANEL, FRONT BUMPER & ETC.

\$1,400.00 *880*

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN MOULDING & ETC. TO EFFECT REPLACE OF REAR TAILGATE.

\$150.00 *120*

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

\$120.00 *60*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$100.00 *50*

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$150.00 *7*

TO CHECK WIRING & CENTRAL LOCKING SYSTEM.

\$80.00 *30*

LABOUR TOTAL \$3,400.00

TING AN

TOTAL

\$10,839.60

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

