

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4509H**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	WING MIRROR RH	CRACKED	1,391.70	1,391.70
	LESS 20% DISCOUNT		-278.34	-278.34
			1,113.36	1,113.36
<b><u>NETT ITEMS</u></b>				
1	REAR DOOR APPS RH (N)	NECESSARY	80.00	80.00
	LESS 20% DISCOUNT		-8.00	-8.00
			72.00	72.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR DOOR ADV. STICKER RH (SN)	NECESSARY	100.00	100.00
1	REAR FENDER ADV. STICKER RH (SN)	NECESSARY	100.00	100.00
			200.00	200.00
<b><u>LABOUR</u></b>				
	PANEL BEATING - REAR FENDER RH		800.00	350.00
	SPRAY PAINT - FRT WRC PIILAR RH		1,200.00	900.00
	CHECK ALL WIRINGS.		50.00	30.00
	TUFF COAT ON AFFECTED PARTS.		30.00	30.00
			2,080.00	1,310.00
<b>GRAND TOTAL</b>			<b>3,465.36</b>	<b>2,695.36</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>2,150.00</b>

Report Ref No. NS/INC22003187/Vvcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**