



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2204275
3 ANSON ROAD #16-00	INV Date	13/07/2022
SPRINGLEAF TOWER	Reference	CC6/CTI22003190/Kpa3q2
SINGAPORE 079909	Code	CTI

### PROFESSIONAL SERVICE FEE

Vehicle No.	SMK 5776A
Insured Veh.	SNB 3921X
Claim No.	SNM22D202402/C02
Policy No.	DMPCSNW00223192100
Accident Date	29/03/2022
Inspection Date	05/04/2022

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI22003190/Kpa3q2 Date: 13/07/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SNB 3921X	Veh. Inspected	SMK 5776A
Policy No.	DMPCSNW00223192100	Coverage (\$)	0.00
Claim No.	SNM22D202402/C02	Excess (\$)	0.00
Assign From		Assign Date	05/04/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA GRACE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GM41207051	Colour	METALLIC BLACK
Odometer	213477 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	SAILUN	5 mm
L/H Front Tyre	185/60 R15	SAILUN	5 mm
R/H Rear Tyre	185/60 R15	SAILUN	6 mm
L/H Rear Tyre	185/60 R15	SAILUN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/03/2022	Inspection Date	05/04/2022
Survey held at	HWA SENG SPRAY PAINTING PTE LTD 160 SIN MING DRIVE #05-11 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 5776A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	LEFT REAR DOOR	BENT / WARPED	904.70	759.60
1	LEFT REAR DOOR STICKER	NECESSARY	48.50	48.50
	LESS 20% DISCOUNT		-190.64	-161.62
			762.56	646.48
<b>LABOUR</b>				
	PANEL KNOCKING .		360.00	300.00
	SPRAY PAINTING.		680.00	400.00
	LABOUR TO TRANSFER DOOR TRIM & ATTACH PARTS.		200.00	60.00
			1,240.00	760.00
<b>GRAND TOTAL</b>			<b>2,002.56</b>	<b>1,406.48</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,100.00</b>

Report Ref No. CC6/CTI22003190/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SMK 5776A

## INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

