

Our Job Ref No : 305511500  
Date : 07/04/22

**COMFORTDELGRO**  
**ENGINEERING**

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK

Fax :

Attn : Mr Thevan

Vehicle Reg No. : SHC2042E

04/04/2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- YN 1232X
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \_\_\_\_\_
  - (b) Labour Charges \_\_\_\_\_
  - Total for Part-By-Part Repair Cost** \$0.00
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
**Final Lumpsum Repair cost** \$1,050.00
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : Ms. Loke YY  
Tel : 62148355  
Fax : 65468156

Signature :   
Name : Thevan  
Date : 22/4/22

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

**COMFORT TRANSPORTATION PTE LTD**

**REPAIR ESTIMATE**

Vehicle No. : SHC2042E

Make : HYUNDAI

Model : IONIQ(G2)

Date: 05/04/22

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
2	REAR BUMPER REINFORCEMENT BRACKET LH RH			\$276.20
1	ANTENNA SMARTKEY		\$138.10	\$40.50
1	REAR BUMPER FOG LAMP			\$201.50
1	LICENCE LAMP			\$85.30
1	REAR BUMPER TOWING COVER			\$98.80
	<b>SUB TOTAL</b>			\$2,029.75
	<b>LESS 20%</b>			\$405.95
	<b>DISCOUNTED TOTAL</b>			<b>\$1,623.80</b>
	REAR NUMBER PLATE WITH TRIM COVER			\$55.00
	REAR BUMPER REVERSE SENSOR			\$180.00
				<b>\$235.00</b>
	<b>Labour Charge</b>			
	PANEL BEATING			\$400.00
	SPRAY PAINTING CHARGE			\$300.00
	CHECK ALL LIGHTING			\$60.00
	REMOVE/REFIX REVERSE SENSOR			\$80.00
	<b>TOTAL LABOUR</b>			<b>\$840.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$2,698.80</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thavan  
 82235769  
 5/4/22 1600  
 LIS repair  
 delays wp

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: