

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4193205


JC NO305511500

STOMER VMS COMFORT TRANSPORTATION PTE LTD STOMER NO 7010045 DRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P) SCOUNT CARD NO.	REGN NO: SHC2042E	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL IONIQ(G2) 05.04.2022 10:05	DATE/TIME IN
	YR OF MANU. 27.02.2019	TARGET DATE
	CHASSIS CODE KMHC851CVKU140880	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 04.04.2022
NATURE: 3P 04.04.2022

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHC2042E YY

Vehicle No.: SHC2042E

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC2042E

Make : HYUNDAI

Model : IONIQ(G2)

Date: 05/04/22

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40 <i>scr</i>
10	REAR BUMPER CLIPS			\$22.00 <i>scr</i>
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25 <i>scr</i>
1	REAR BUMPER REINFORCEMENT			\$394.80 <i>scr</i>
2	REAR BUMPER REINFORCEMENT BRACKET LH RH			\$276.20 <i>scr</i>
1	ANTENNA SMARTKEY		\$138.10	\$40.50 <i>scr</i>
1	REAR BUMPER FOG LAMP			\$201.50 <i>scr</i>
1	LICENCE LAMP			\$85.30 <i>scr</i>
1	REAR BUMPER TOWING COVER			\$98.80 <i>scr</i>
	SUB TOTAL			\$2,029.75
	LESS 20%			\$405.95
	DISCOUNTED TOTAL			\$1,623.80
	REAR NUMBER PLATE WITH TRIM COVER			\$55.00 <i>lrg</i>
	REAR BUMPER REVERSE SENSOR			\$180.00 <i>cut</i>
				\$235.00
	Labour Charge			
	PANEL BEATING			\$400.00 <i>350</i>
	SPRAY PAINTING CHARGE			\$300.00 <i>250</i>
	CHECK ALL LIGHTING			\$60.00 <i>30</i>
	REMOVE/REFIX REVERSE SENSOR			\$80.00 <i>30</i>
	TOTAL LABOUR			\$840.00
	ESTIMATE TOTAL			\$2,698.80

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Theran
 82235769
 5/4/22 1600
 L/S repair
 delays w/p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: