

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

| Affiliated to Federation Internationale Des Experts En Automobile |  |   |                 |                        |  |
|---|--|---|-----------------|------------------------|--|
|   | ECICS LTD  |   | Ref:            | CS3/ICS22003196/Tqy3e2 |  |
|   | 10 EUNOS ROAD<br>SINGAPORE POS<br>SINGAPORE 4086   | T CENTRE #09-04A  | Date:           | 02/09/2022             |  |
|   |  |   | Code:           | ICS                    |  |
| 1.  | Policy Particulars :- (THIRD PARTY CLAIM)  |   |                 |                        |  |
|   | Insured Veh.   | SJU 4755A   | Veh. Inspected  | GBG 5317T              |  |
|   | Policy No.   | MPC21P00109700  | Coverage (\$)   | 0.00                   |  |
|   | Claim No.  | DMPC2200139H  | Excess (\$)     | 0.00                   |  |
|   | Assign From  | GENEVIEVE KUA   | Assign Date     | 06/04/2022             |  |
| 2. Vehicle Particulars & Condition                                |  |   |                 |                        |  |
|   | Make & Model   |   | c.c             | 0                      |  |
|   | Engine No.   | HIDDEN  | Year of Reg.    | 2017                   |  |
|   | Chassis No.  | JTFAT35Y60K208813   | Colour          |                        |  |
|   | Odometer -   |   | Steering        |                        |  |
|   | Brakes   |   | Modification    |                        |  |
|   | General  |   |                 |                        |  |
| 3. Conditions of Tyres  |  |   |                 |                        |  |
|   |  | Size  | Make            | Balance                |  |
|   | R/H Front Tyre   |   |                 | mm                     |  |
|   | L/H Front Tyre   |   |                 | mm                     |  |
|   | R/H Rear Tyre  |   |                 | mm                     |  |
|   | L/H Rear Tyre  |   |                 | mm                     |  |
| 4.  | Description of Damages   |   |                 |                        |  |
|   |  |   |                 |                        |  |
| 5.  | . General Information  |   |                 |                        |  |
|   | Accident Date  | 02/04/2022  | Inspection Date | 16/06/2022             |  |
|   | Survey held at   | PAUL HOE BATTERIES & MOTOR SERVICES                           |                 |                        |  |
|   |  | BLK 1 KAKI BUKIT AVE 6<br>#01-109 AUTOBAY<br>SINGAPORE 417833 |                 |                        |  |
| 5a. Remarks   |  |   |                 |                        |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                 |                        |  |