



PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857

TEL : 6474 3323 FAX : 6264 6786

EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : 24 BENOI SECTOR
CONTACT NO : 6474 3323
FAX NO : 6264 6786
REFERENCE : PAC/OD/0038/2022/GW
DATE : 7-Apr-22
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 Robinson Road

#09-01

Singapore 068897

ATTN: MOTOR CLAIMS DEPT

Tel: 6297 2529 Fax: 6297 1956

OWNER'S NAME : MR ROY CHAN KUM WAH
ADDRESS : 37 TAMAN SERASI
#08-31
SINGAPORE 257724
TELEPHONE : HP +65 96792970
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : SP2000385710/2021
VEHICLE NO : **EB 111 T**
MODEL CODE : BMW M2 COUPE 4.0
MODEL YEAR : 28/7/2016
ENGINE NO : 05119580N55B30A
CHASSIS NO : WBS1H92030V790713
MILEAGE : -
DATE IN :
ESTIMATED BY : ALLAN WU
ACCIDENT DATE : 4-Apr-22
PLACE OF ACCIDENT : THE TRAFFIC LIGHT JCT



24 BENOI SECTOR, SINGAPORE 629857
TEL : 6474 3323 FAX : 6264 6786
EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE EB 111 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WAHSE ASSY.	S/N	\$ 150.00	✓
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 400.00	200
3	TO RESPRAY FRONT BUMPER.		\$ 400.00	200
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 150.00	✓
TOTAL LABOUR CHARGES		:	\$ 1,100.00	

PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857

TEL : 6474 3323 FAX : 6264 6786

EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. EB 111 T

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT	
1 FRONT BUMPER ✓ DE	1	\$	990.00	
2 FRONT BUMPER SIDE GUIDE - LH / RH ?	2	\$	77.00	
3 FRONT BUMPER SIDE GUIDE - LH / RH LOWER ?	2	\$	62.00	
4 FRONT BUMPER SIDE AIR DUCT - LH / RH ?	2	\$	121.00	
5 FRONT BUMPER LOGO " BMW " ✓ NEC	1	\$	83.00	
6 RADIATOR GRILLE - LH / RH ✓ SCR	2	\$	616.00	
7 FRONT FOG LAMP COVER - LH / RH ?	2	\$	154.00	
8 FRONT BUMPER LOWER SPOILER - LH / RH ?	2	\$	2,332.00	
9 FRONT BUMPER LOWER GRILLE ?	1	\$	88.00	
8 SUNDRIES ?		\$	200.00	
TOTAL PARTS CHARGES	:	\$	4,723.00	
TOTAL LABOUR CHARGES	:	\$	1,100.00	
GRAND TOTAL	:	\$	5,823.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857


TEL : 6474 3323 FAX : 6264 6786

EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

NAME : Guo Qiang - LKK
SURVEYED DATE : 11/04/2022
AUTHORISED DATE :
EXCESS COST : Not Authorised
LIABILITY : Excess: TBA
REMARKS : 3 Days
Before paint photos

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6474 3323 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOCARE CENTRE



JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT