

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0263/2022/NK
DATE : 05-Apr-22
WIP : 17890

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR EUGENE TAN KEAT MENG
ADDRESS : BLK 119 POTONG PASIR AVE 1
#07-1022
SINGAPORE 350119
TELEPHONE : HP +65 96884011
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900251582-01
VEHICLE NO : **SLC 930 H**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 29-11-2019
ENGINE NO : CZD 886134
CHASSIS NO : WAUZZZF33L1010150
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Mar-22
PLACE OF ACCIDENT : 61 PASIR RIS DR 1 PETROL KIOSK

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLC 930 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAILLIGHTS AND REAR LID WIPER ASSY.	S/N \$ 480.00	✓
3	TO RENEW REAR WINDSCREEN TO FACILITATE THE RENEWAL OF REAR LID.	S/N \$ 480.00	✓
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$ 400.00	✓
5	TO CARRY WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00 150	
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. REORGANIZE CRASH MANAGERMENTS COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00 1000	
7	TO RESPRAY REAR BUMPER, REAR LID AND REAR END PANELLING.	\$ 3,000.00 1100	
8	TO CARRY OUT TOWING FROM ACCIDENT SCENE.	S/N \$ 280.00	X
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>8,192.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 930 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Deformed</i>	1	\$ 1,738.00	✓
2	REAR BUMPER FIXING PART REAR <i>new</i>	1	\$ 220.00	+
3	REAR BUMPER SPOILER <i>Deformed</i>	1	\$ 510.00	✓
4	REAR TOW EYE COVER <i>new</i>	1	\$ 48.00	x
5	REAR CROSS REINFORCEMENT BRACKET CENTRE ?	1	\$ 108.00	?
6	REAR BUMPER BRACKET <i>new</i>	1	\$ 53.00	+
7	REAR LIGHT REFLECTOR LH / RH	2	\$ 92.00	+
8	REAR ANTENNA AERIAL <i>new</i>	1	\$ 79.00	+
9	REAR LID CONTROL UNIT <i>new</i>	1	\$ 454.00	+
10	REAR BUMPER REINFORCEMENT BEAM ?	1	\$ 693.00	?
11	REAR BUMPER HOLDING STRAP LH / RH	2	\$ 64.00	+
12	REAR BUMPER GUIDE SECTION LH / RH	2	\$ 142.00	+
13	REAR PARKING AID SENSOR	2	\$ 998.00	+
14	REAR SENSOR SEAL RING	4	\$ 10.00	+
15	REAR LID <i>Dented</i>	1	\$ 3,767.00	✓
16	REAR LID PACKING ADHESIVE <i>new</i>	1	\$ 21.00	✓
17	BOLTS AND NUTS <i>new</i>	4	\$ 18.00	+
18	REAR LID ATTACHMENTS PARTS <i>new</i>	1	\$ 393.00	+
19	REAR LID GASKET <i>new</i>	1	\$ 229.00	+
20	REAR LID LOCK - COVER <i>new</i>	1	\$ 8.00	x
SUB TOTAL SPARE PARTS		:	\$ 9,645.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 930 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	AUDI CHROME LOGO	1	\$ 144.00	✓
22	AUDI "Q3" CHROME EMBLEM	1	\$ 104.00	✓
23	REAR WINDSCREEN	1	\$ 1,064.00	✓
24	REAR WINDSCREEN PRIMER	1	\$ 22.00	✓
25	REAR WINDSCREEN SPOILER LH / RH	2	\$ 470.00	✓
26	REAR LID SPOILER ATTACHEMENTS PARTS	2	\$ 16.00	✓
27	REAR WHEEL COVER REAR LH / RH	2	\$ 566.00	✓
28	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	+
29	REAR NO PLATE	S/N	\$ 60.00	+
30	SUNDRIES	1	\$ 400.00	?
TOTAL SPARE PARTS		:	\$ 12,691.00	
TOTAL LABOUR CHARGES		:	\$ 8,192.00	
GRAND TOTAL		:	\$ 20,883.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian Lim
SURVEYED DATE : 06/04/22
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 94 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT