

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hor, Yinrul

Date: 09 Sep 2022

Preliminary Advice

Vehicle No	: SLF5683Y	Accident Date	: 01/04/2022
Make	: AUDI Q7	Policy No.	: 2100480662-05
Assignment Date	: 07/04/2022	Excess	: S\$1,000.00
Date of Inspection	: 06/04/2022	Est. Duration of Repair	: 16
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	61,457.00	(Estimate \$60,888 + Supplementary \$569.00)
Revised Amount	:S\$	47,725.00	
Check Items (Estimated)	:S\$	1,664.00	
Total	:S\$	49,389.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	134,000.00
COE / PARF Rebate	:S\$	80,224.00
Salvage Value	:S\$	
Margin for Repair	:S\$	53,776.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Kindly approve on supplementary