



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0264/2022/NK  
**DATE** : 5-Apr-22  
**WIP** : 18567

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/4/22**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**Hi Adrian**

**16 days exclude 3 Sundays**

**Johnny Boo - 28 Sep 22**

**OWNER'S NAME** : MR ALESSANDRO PERROTTA  
**ADDRESS** : 19 NASSIM HILL  
#07-04, NASSIM WOOD  
SINGAPORE 258482  
**TELEPHONE** : HP +65 96254063  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 2100480662-05  
**VEHICLE NO** : **SLF 5683 Y**  
**MODEL CODE** : AUDI Q7 2.0 TFSI QU.  
**MODEL YEAR** : 30/8/2016  
**ENGINE NO** : CYR012514  
**CHASSIS NO** : WAUZZZ4M4GD060216  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 1-Apr-22  
**PLACE OF ACCIDENT** : ALONG PASIR PANJANG

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLF 5683 Y**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00 \$	<b>360.00</b>
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	S/N \$	480.00 \$	<b>480.00</b>
3	TO RENEW REAR WINDSCREEN TO FACILITATE THE RENEWAL OF LHS REAR LID	S/N \$	480.00 \$	<b>480.00</b>
4	TO RENEW LHS 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER.	S/N \$	300.00 \$	<b>300.00</b>
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$	200.00 \$	<b>150.00</b>
6	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00 \$	<b>1,600.00</b>
7	<b>Added labour - see attached</b>		<b>\$ 400.00</b>	<b>\$ 400.00</b>
8	TO REMOVE AND REINSTALL REAR SEAT. BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00 \$	<b>1,600.00</b>
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 5,420.00</b>	<b>\$ 5,370.00</b>

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLF 5683 Y**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>C/F</i>		\$ <b>5,370.00</b>
8	TO SET UP AND PLACED VEHICLE IN ALUMINIUM BAY	S/N	\$ 1,800.00	\$ <b>1,800.00</b>
9	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD LHS REAR FENDER. TO REPAIR LHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	7,500.00	\$ <del>6,600.00</del> 5900
10	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, REAR LID, HINGES, LHS REAR FENDER, LHS REAR DOOR, DOOR COVER, LHS SILL PANEL, ROOF CHANNEL, DOOR ENTRANCE, DRAIN CHANNEL, REAR END PANELLING, LHS REAR DOOR WHEEL ARCH TRIM AND BOTH REAR WHEEL ARCH TRIMS.	\$	9,500.00	\$ <b>3,900.00</b>
11	TO CARRY OUT ALUMINIUM PRIMER WORKS	S/N	\$ 900.00	\$ <b>900.00</b>
12	TO REMOVE AND REINSTALL LHS ROOF RAIL.	S/N	\$ 280.00	<i>nil</i>
13	TO REMOVE AND REINSTALL ROOFTOP PANEL CARRIER	S/N	\$ 480.00	<i>nil</i>
<b>TOTAL LABOUR CHARGES</b>		:	\$ <b>20,460.00</b>	\$ <b>18,570.00</b>



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLF 5683 Y**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		<b>\$ 18,570.00</b>
14	TO RENEW RHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	280.00	<b>\$ 280.00</b>
15	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	<b>\$ 192.00</b>
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 26,352.00</b>	<b>\$ 19,042.00</b>

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 5683 Y - REAR**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT		REMARKS
1	REAR BUMPER	1	\$ 1,451.00	\$	<b>1,160.80</b>
2	REAR BUMPER COVER	1	\$ 2,201.00	\$	<b>1,760.80</b>
3	REAR BUMPER FIXING PARTS	1	\$ 217.00		
4	REAR BUMPER SPOILER	1	\$ 1,407.00	\$	<b>1,125.60</b>
5	REAR BUMPER GUIDE SECTION	1	\$ 71.00	\$	<b>56.48</b>
6	REAR BUMPER SENSOR	1		TBC	
7	REAR BUMPER SEAL RING	1	\$ 10.00		
8	TAILLIGHT BULB	1	\$ 402.00	\$	<b>321.60</b>
9	LED TAILLIGHT	1	\$ 2,279.00	\$	<b>1,823.20</b>
10	REAR LID	1	\$ 6,480.00	\$	<b>5,184.00</b>
11	REAR LID ATTACHMENTS PARTS	1	\$ 359.00		
12	REAR LID HINGE LH / RH	2	\$ 342.00		
13	FLAP LOCK COVER CAP	1	\$ 13.00		
14	REAR LID GASKET	1	\$ 325.00		
15	PACKING ADHESIVE	1	\$ 21.00	\$	<b>16.72</b>
16	AUDI CHROME LOGO	1	\$ 144.00	\$	<b>114.80</b>
17	AUDI CHROME ' Q7 ' EMBLEM	1	\$ 104.00	\$	<b>82.80</b>
18	AUDI CHROME "TFSI" EMBLEM	1	\$ 104.00	\$	<b>82.80</b>
19	AUDI CHROME " QUATTRO " EMBLEM	1	\$ 104.00	\$	<b>82.80</b>
20	REAR WINDSCREEN	1	\$ 1,307.00	\$	<b>1,045.60</b>
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 17,341.00</b>	<b>\$</b>	<b>12,858.00</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:       REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                   SPARE PARTS ARE SPECIAL NETT.

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 5683 Y**

			<b>DAMAGED PARTS &amp; PRICES</b>	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
<i>c/f</i>				<b>\$ 12,858.00</b>
21	REAR WINDSCREEN PRIMER	2	\$ 44.00	<b>\$ 34.72</b>
22	REAR WINDSCREEN SPOILER REAR LH / RH	2	\$ 514.00	<b>\$ 410.40</b>
23	REAR WINDSCREEN FOAM STRIPS	1	\$ 153.00	<b>\$ 122.00</b>
24	REAR SPOILER FIXING PARTS	1	\$ 69.00	
25	SECTIONAL PARTS LH	1	\$ 7,776.00	<b>\$ 6,220.80</b>
26	1/4 GLASS	1	\$ 1,053.00	<b>\$ 842.40</b>
27	SILL TRIM STRIP LH	1	\$ 182.00	
28	SPOILER REAR LH	1	\$ 40.00	
29	WHEEL HOUSING LINER	1	\$ 347.00	
30	WHEEL COVER REAR LH / RH	2	\$ 794.00	<b>\$ 635.20</b>
31	REAR DOOR COVER REAR LH UPPER / LH LOWER	1	\$ 880.00	
32	ALUMINIUM RIM	1	\$ 2,266.00	<b>\$ 1,812.80</b>
33	RUBBER VALVE	1	\$ 4.00	
34	STATIC MIXER	3	\$ 12.00	<b>\$ 27.60</b>
35	2 PACK EPOXY ADHESIVE	1	\$ 122.00	<b>\$ 97.20</b>
36	ALUMINIUM POWDER	1	\$ 637.00	<b>\$ 509.60</b>
37	HARDENER	1	\$ 232.00	<b>\$ 185.20</b>
38	ALUMINIUM PRIMER	1	\$ 233.00	
39	CLEANING BLOCK	1	\$ 96.00	<b>64.16</b>
40	SPARE PARTS GASKET LH	1	\$ 157.00	
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 15,611.00</b>	<b>\$ 23,820.08</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                  SPARE PARTS ARE SPECIAL NETT.

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 5683 Y**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 23,820.08
40	SPARE PARTS BASIC PLATE LH	1	\$ 116.00	
41	SPARE PARTS ALUMINIUM FRONT LH	1	\$ 288.00	
42	ACYRLIC SEALANT	S/N	\$ 180.00	\$ 180.00
43	CAVITY WAX	S/N	\$ 140.00	\$ 140.00
44	STONE CHIP	S/N	\$ 180.00	\$ 180.00
45	METAL FILLER POWDER	S/N	\$ 280.00	\$ 280.00
46	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
47	1/4 GLASS SEALANT	S/N	\$ 100.00	\$ 100.00
48	<b>Added parts - see attached</b>		\$ 457.90	\$ 390.32
49	SUNDRIES		\$ 500.00	\$ 67.04
<b>TOTAL SPARE PARTS</b>			<b>\$ 35,393.90</b>	<b>\$ 25,357.44</b>
<b>TOTAL LABOUR CHARGES</b>			<b>\$ 26,352.00</b>	<b>\$ 19,042.00</b>
<b>GRAND TOTAL</b>			<b>\$ 61,745.90</b>	<b>\$ 44,399.44</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.  
 BL-18/07/22



## Supplementary Estimate-1

GST Reg No. 19-9902271-W

<b>AIG Asia Pacific Insurance Pte Ltd</b> 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept <b>Tel: 6841 0055 / Fax: 6256 4315</b>		<b>Estimate No.</b> <b>Date</b> <b>Service Advisor</b> <b>Pages</b> <b>Regn No</b> <b>Model No</b>	PA/OD/0264/2022/NK 29-Jun-22 CHANG 1 of 1 SLF 5683 Y AUDI Q7 2.0 TFSI QU
Quantity	Description	Unit Price	Amount
<b>Labours</b>			
1	TO APPLY SOLAR FILM ON REAR WINDSCREEN AND LH 1/4 GLASS.	S/N \$ 400.00	\$ <b>400.00</b>
<b>GRAND TOTAL</b>		<b>\$ 400.00</b>	<b>\$ 400.00</b>

For Premium Automobiles Pte Ltd

---

 Authorised Signature



## Supplementary Estimate

GST Reg No. 19-9902271-W

<b>AIG Asia Pacific Insurance Pte Ltd</b> 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept <b>Tel: 6841 0055 / Fax: 6256 4315</b>		<b>Estimate No.</b> <b>Date</b> <b>Service Advisor</b> <b>Pages</b> <b>Regn No</b> <b>Model No</b>	PA/OD/0264/2022/NK 6-Sep-22 GLORY 1 of 1 SLF 5683 Y AUDI Q7 2.0 TFSI QU
Quantity	Description	Unit Price	Amount
<b>Labours</b>			
1	COUNTERSUNK RIVET	\$ 115.00	\$ <b>92.00</b>
2	POP RIVET	\$ 30.00	\$ <b>24.00</b>
3	2 PK PLASTIC ADHESIVE	\$ 62.00	\$ <b>49.12</b>
4	REAR VENT TRIM	\$ 80.00	
5	SEAL FOR SILL PANEL LHS	\$ 282.00	\$ <b>225.20</b>
<b>GRAND TOTAL</b>		<b>\$ 569.00</b>	<b>\$ 390.32</b>

For Premium Automobiles Pte Ltd

---

 Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT