



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0264/2022/NK  
DATE : 05-Apr-22  
WIP : 18567

*Hui Rong*

*16 Days*

*\$44393.44.*

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/4/22

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
Attn: Motor Claims Dept  
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ALESSANDRO PERROTTA  
ADDRESS : 19 NASSIM HILL  
                  #07-04, NASSIM WOOD  
                  SINGAPORE 258482  
TELEPHONE : HP +65 96254063  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 2100480662-05  
VEHICLE NO : SLF 5683 Y  
MODEL CODE : AUDI Q7 2.0 TFSI QU.  
MODEL YEAR : 30-08-2016  
ENGINE NO : CYR012514  
CHASSIS NO : WAUZZZ4M4GD060216  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 01-Apr-22  
PLACE OF ACCIDENT : ALONG PASIR PANJANG



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLF 5683 Y**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY. S/N \$	480.00	✓
3	TO RENEW REAR WINDSCREEN TO FACILITATE THE RENEWAL OF LHS REAR LID S/N \$	480.00	✓
4	TO RENEW LHS 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER. S/N \$	300.00	✓
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS. S/N \$	<del>200.00</del> 150	
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY. S/N \$	<del>1,600.00</del>	
7	TO REMOVE AND REINSTALL REAR SEAT. BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC. S/N \$	1,600.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 5,020.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLF 5683 Y**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
8	TO SET UP AND PLACED VEHICLE IN ALUMINIUM BAY	S/N \$ 1,800.00	✓
9	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD LHS REAR FENDER. TO REPAIR LHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S <del>6800</del> 7,500.00	5900 7 x 600 = 4200 Rear Protect = 300 4500
10	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, REAR LID, HINGES, LHS REAR FENDER, LHS REAR DOOR, DOOR COVER, LHS SILL PANEL, ROOF CHANNEL, DOOR ENTRANCE, DRAIN CHANNEL, REAR END PANELLING, LHS REAR DOOR WHEEL ARCH TRIM AND BOTH REAR WHEEL ARCH TRIMS.	S 3900 9,500.00	5.5 x 600 = 3300 Door Protector = 200 Wheel Arch XL = 400 3900
11	TO CARRY OUT ALUMINIUM PRIMER WORKS	S/N \$ 900.00	✓
12	TO REMOVE AND REINSTALL LHS ROOF RAIL.	S/N \$ 280.00	? X
13	TO REMOVE AND REINSTALL ROOFTOP PANEL CARRIER	S/N \$ 480.00	? X
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 20,460.00</b>	

7 days (Fender) + 1 Day (Tailgate) = 8 days.  
 8 days x 700 (Aluminium cutting) = 5600  
 Door Protect = 300  
 5600 + 300 = 5900.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLF 5683 Y**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
14	TO RENEW RHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 280.00	✓
15	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 25,952.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 5683 Y - REAR**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Rehd</i>	1	S 1,451.00	✓ 1160.8
2	REAR BUMPER COVER <i>Rehd</i>	1	S 2,201.00	✓ 1760.8
3	REAR BUMPER FIXING PARTS <i>Acu</i>	1	S 217.00	+
4	REAR BUMPER SPOILER <i>lit</i>	1	S 1,407.00	✓ 1125.6
5	REAR BUMPER GUIDE SECTION <i>Acu Dmgd.</i>	1	S ✓ 71.00	± 56.48 condition
6	REAR BUMPER SENSOR <i>Acu</i>	1	TBC	+
7	REAR BUMPER SEAL RING <i>Acu</i>	1	S 10.00	+
8	TAILLIGHT BULB <i>Acu</i>	1	S ✓ 402.00	± 321.6 condition
9	LED TAILLIGHT <i>could</i>	1	S 2,279.00	✓ 1823.2
10	REAR LID <i>Rehd</i>	1	S 6,480.00	✓ 5184
11	REAR LID ATTACHMENTS PARTS <i>Acu</i>	1	S 359.00	+
12	REAR LID HINGE LH / RH <i>2 Acu</i>	2	S 342.00	+
13	FLAP LOCK COVER CAP	1	S 13.00	+
14	REAR LID GASKET <i>Acu</i>	1	S 325.00	+
15	PACKING ADHESIVE <i>Acu</i>	1	S 21.00	✓ 16.72
16	AUDI CHROME LOGO	1	S 144.00	✓ 114.8
17	AUDI CHROME "Q7" EMBLEM <i>2 Acu</i>	1	S 104.00	✓ 82.8
18	AUDI CHROME "TFSI" EMBLEM	1	S 104.00	✓ 82.8
19	AUDI CHROME "QUATTRO" EMBLEM	1	S 104.00	✓ 82.8
20	REAR WINDSCREEN <i>NEC</i>	1	S 1,307.00	✓ 1045.6
<b>SUB TOTAL SPARE PARTS</b>		:	<b>\$ 17,341.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 5683 Y**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	REAR WINDSCREEN PRIMER <i>neu</i>	2	\$ 44.00	✓ 34.72
22	REAR WINDSCREEN SPOILER REAR LH / RH <i>neu</i>	2	\$ 514.00	✓ 410.4
23	REAR WINDSCREEN FOAM STRIPS <i>neu</i>	1	\$ 153.00	✓ 122
24	REAR SPOILER FIXING PARTS <i>neu</i>	1	\$ 69.00	+
25	SECTIONAL PARTS LH <i>Dented</i>	1	\$ 7,776.00	✓ 6220.8
26	1/4 GLASS <i>neu</i>	1	\$ 1,053.00	✓ 842.4
27	SILL TRIM STRIP LH <del>neu</del> <i>nn</i>	1	\$ 182.00	+X
28	SPOILER REAR LH <i>neu</i>	1	\$ 40.00	+X
29	WHEEL HOUSING LINER <i>neu</i>	1	\$ 347.00	+X
30	WHEEL COVER REAR LH / RH <i>neu</i>	2	\$ 794.00	✓ 635.2
31	REAR DOOR COVER REAR LH UPPER / LH LOWER <i>neu</i>	1	\$ 880.00	x
32	ALUMINIUM RIM <i>at</i>	1	\$ 2,266.00	✓ 1812.8
33	RUBBER VALVE <i>neu</i>	1	\$ 4.00	+
34	STATIC MIXER	1	\$ 12.00	✓ 27.6
35	2 PACK EPOXY ADHESIVE	1	\$ 122.00	✓ 97.2
36	ALUMINIUM POWDER	1	\$ 637.00	✓ 509.6
37	HARDENER	1	\$ 232.00	✓ 185.2
38	ALUMINIUM PRIMER <i>neu</i>	1	\$ 233.00	✓ x condition
39	CLEANING BLOCK <i>neu</i>	1	\$ 96.00	✓ 64.16
40	SPARE PARTS GASKET LH <i>neu</i>	1	\$ 157.00	+
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 15,611.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 5683 Y**

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
40	SPARE PARTS BASIC PLATE LH <i>Ne ne</i>	1	\$ 116.00	? x condition	
41	SPARE PARTS ALUMINIUM FRONT LH <i>Ne ne</i>	1	\$ 288.00	? x condition	
42	ACYRLIC SEALANT	S/N	\$ 180.00	✓	
43	CAVITY WAX	S/N	\$ 140.00	✓	
44	STONE CHIP	S/N	\$ 180.00	✓	
45	METAL FILLER POWDER	S/N	\$ 280.00	✓	
46	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	✓	
47	1/4 GLASS SEALANT	S/N	\$ 100.00	✓	
48	SUNDRIES <i>Ne</i>		\$ 500.00	? 67.04 condition	
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 34,936.00</b>		
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 25,952.00</b>		
<b>GRAND TOTAL</b>		:	<b>\$ 60,888.00</b>		

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian Lj  
SURVEYED DATE : 06/04/22  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : Not Authorised, 16 Days. *[Signature]*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT