



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Tang Hwee Koon (chen Huijun)	Cust No/Name	/Tang Hwee Koon (Chen Huijun)
26A Saint George's Lane	Reg No/Reg Date	SLT6982D / 08/11/201
27-23	Date In/Mileage	/ 0
Singapore 321026	Chassis No	MMCXTA03AJH001841
Contact No Mobile: 90690822	Engine No	3A92UGK7206
	Make/Model	MIT/18MY SPACE STAR 1.2 CVT (T81)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
CSM00041	Cash	05/04/2022/ 12:22	TLK	282 / Kevin Leong	22246				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E PNT88000	REPAIR ON REAR RH DOOR & REAR RH FENDER								1280.00
E PNT98000	PAINT WORK ON REAR RH DOOR & REAR RH FENDER								1650.00
M SUNDRY	PERFORM RUST PREVENTION								100.00
M SUNDRY	TO APPLY SEALANT ON AFFECTED AREA								50.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								120.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								280.00
M SUNDRY	SUNDRIES								50.00

Confirm & accepted by

7% GST on **Nett** 3,530.00 3,530.00
 247.10

Total Payable 3,777.10

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.