

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 3527C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	REPAIRED SEE LABOUR	1,528.00	-
1	FRONT LH SHOCK ABSORBER	NOT CHANGED	881.00	-
1	FRONT LH SHOCK ABSORBER TOP MOUNTING	NOT CHANGED	322.00	-
1	FRONT LH LOWER ARM	NOT CHANGED	592.00	-
1	FRONT LH KNUCKLE ARM	NOT CHANGED	1,014.00	-
1	FRONT LH WHEEL HUB & BEARING	NOT CHANGED	207.00	-
1	FRONT STABILIZER BAR	SERVICEABLE / REUSE	204.00	-
1	FRONT STABILIZER BAR LH LINK ROD	NOT CHANGED	84.00	-
1	STEERING RACK & PINION LH TIE ROD	NOT CHANGED	189.00	-
	LESS 10% DISCOUNT		-502.10	-
			4,518.90	-
1	FRONT LH SPORTS RIMS (SN)	REPLACED	1,314.00	800.00
	LESS 10% DISCOUNT		-131.40	-
			1,182.60	800.00
	<u>LABOUR</u>			
	TO REMOVE, JACK OUT, STRAIGHTEN, PANEL BEATING, ALIGN AND RENEW REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		800.00	200.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.		800.00	440.00
	TO REMOVE, REFIX FRONT LH DAMAGE UNDER CARRIAGES.	NOT NECESSARY	300.00	-
	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST.		80.00	60.00
	TO SUPPLIED AND APPLIED ANTI RUST TREATMENTS.	NOT NECESSARY	50.00	-
			2,030.00	700.00
	GRAND TOTAL		7,731.50	1,500.00

Report Ref No. CS/LAW22003223/Kqce2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,200.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/LAW22003223/Kqce2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser