



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ASCENTSIA LAW CORPORATION 10 ANSON ROAD, #03-22, INTERNATIONAL PLAZA, SINGAPORE 079903			Ref: CS/LAW22003223/Kqce2	
			Date: 05/05/2022	
			Code: L173	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	GBA 5711U		Veh. Inspected	SKR 3527C
Policy No.			Coverage (\$)	0.00
Claim No.	CK/YSY/19.022977		Excess (\$)	0.00
Assign From	LIM HUI YING		Assign Date	30/03/2022
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ CLA180 (A)		c.c	1595
Engine No.	HIDDEN		Year of Reg.	2015
Chassis No.	WDD1173422N137418		Colour	METALLIC DARK PURPLE
Odometer	169212 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	STANDARD ALLOY RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		235/40Z R18	PIRELLI	9 mm
L/H Front Tyre		235/40Z R18	PIRELLI	9 mm
R/H Rear Tyre		235/40Z R18	PIRELLI	9 mm
L/H Rear Tyre		235/40Z R18	PIRELLI	9 mm
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	06/12/2019		Inspection Date	11/04/2022
Survey held at	SZE KANG AUTOMOBILE SPRAYING SERVICES BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #03-17 AMK AUTO POINT . SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	