



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LEGAL SOLUTIONS LLC 80 RAFFLES PLACE #44-05 UOB PLAZASINGAPORE 048624			Ref: CS/LAW22003223/Kqce2	
			Date: 05/05/2022	
			Code: L163	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	GBA 5711U	Veh. Inspected	SKR 3527C
	Policy No.		Coverage (\$)	0.00
	Claim No.	LIH/1023956/NTUC	Excess (\$)	0.00
	Assign From	LIM HUI YING	Assign Date	30/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ CLA180 (A)	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WDD1173422N137418	Colour	METALLIC DARK PURPLE
	Odometer	169212 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/40Z R18	PIRELLI	9 mm
	L/H Front Tyre	235/40Z R18	PIRELLI	9 mm
	R/H Rear Tyre	235/40Z R18	PIRELLI	9 mm
	L/H Rear Tyre	235/40Z R18	PIRELLI	9 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	06/12/2019	Inspection Date	11/04/2022
	Survey held at	SZE KANG AUTOMOBILE SPRAYING SERVICES BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #03-17 AMK AUTO POINT . SINGAPORE 568047		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	