

### SERVICE ESTIMATE

##### - C00001      SL: SERVICE SALES - PC

Mr Nick Lim  
 #02-04 Lorong H Telok Kurau  
 The Bale

Singapore 425991

Closed by .... : Juan Paulo Bongon Ba  
 Svc Consultant :  
 Remarks ..... : Mr Nick Lim

GST Reg.No:M28920628X

Inv.No. . . : B&P                      0    Page 1  
 Inv.date. . : 06/04/2022  
 WIP No. . . : 20069  
 Veh.In/Out:  
 \*Tel.No. . . : Mobile: 98472080  
 Reg.No. . . : SMX3417G  
 Reg.date . . : 16/01/2020  
 Mileage .. : 0  
 Chassis No: VF1RFA00963212476

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE BONNET, FRT BUMPER, RADIATOR GRILLE, LOGO, HEADLAMP LH/RH, LOWER MESH GRILLE, SPOILER, ETC	0	1650.00	0		1,650.00	S
800	TO SPRAY BONNET, FRT BUMPER, REINFORCEMENT, ETC	0	2000.00	0		2,000.00	S
802	TO REPLACE FRONT SUPPORT PANEL ETC	0	2200.00	0		2,200.00	S
802	TO VACUUM & TOP UP AIRCON GAS	0	600.00	0		600.00	S
287	TO REMOVE & REPLACE DASHBOARD, AIRBAG COMPONENTS, ETC	0	4800.00	0		4,800.00	S
287	TO REPLACE SEAT BELT & SEAT BE BUCKLE FRONT & REAR.	0	3600.00	0		3,600.00	S
287	TO RESET AIRBAG MODULE SYSTEM	0	1200.00	0		1,200.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00	S

### SERVICE ESTIMATE

#### - C00001      SL: SERVICE SALES - PC

Mr Nick Lim  
 #02-04 Lorong H Telok Kurau  
 The Bale

Singapore 425991

Closed by .... : Juan Paulo Bongon Ba  
 Svc Consultant :  
 Remarks ..... : Mr Nick Lim

GST Reg.No:M28920628X  
 0 Page 2  
 Inv.No. . : B&P  
 Inv.date. : 06/04/2022  
 WIP No. . : 20069  
 Veh.In/Out:  
 \*Tel.No. . : Mobile: 98472080  
 Reg.No. . : SMX3417G  
 Reg.date . : 16/01/2020  
 Mileage .. : 0  
 Chassis No: VF1RFA00963212476

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
R06	NUMBER PLATE & HOLDER	0	60.00	0		60.00	S
	BUMPER FRT GS4	1.0 EA	1457.30			1,457.30	S
	BUMPER FRT TOW COVER	1.0 EA	117.00			117.00	S
	BUMPER FRT SUPPORT B	1.0 EA	132.90			132.90	S
	BUMPER UNDER COVER F	1.0 EA	617.80			617.80	S
	CONVERGENT AIR GUIGE	1.0 EA	300.90			300.90	S
	FOG LAMP FRT INNER B	1.0 EA	197.90			197.90	S
	BUMPER LOWER FRT GS4	1.0 EA	473.80			473.80	S
	BUMPER FRT CENTER IN	1.0 EA	239.10			239.10	S
	BUMPER FRT TOP INNER	1.0 EA	458.40			458.40	S
	FOG LAMP MOULDING OU	1.0 EA	261.40			261.40	S
	FOG LAMP COVER CHORM	1.0 EA	261.40			261.40	S
	SUPPORT BRACKET, HEA	2.0 EA	125.60			251.20	S
	SUPPORT BRACKET, HEA	1.0 EA	125.60			125.60	S
	BUMPER MOUDLING CLIP	10.0 EA	4.00			40.00	S
	BUMPER BRACKET FRT R	1.0 EA	154.60			154.60	S
	BUMPER BRACKET FRT L	1.0 EA	154.60			154.60	S

### SERVICE ESTIMATE

##### - C00001      SL: SERVICE SALES - PC

Mr Nick Lim  
 #02-04 Lorong H Telok Kurau  
 The Bale

Singapore 425991

Closed by .... : Juan Paulo Bongon Ba  
 Svc Consultant :  
 Remarks ..... : Mr Nick Lim

GST Reg.No:M28920628X  
 Inv.No. . . : B&P                    0    Page 3  
 Inv.date. . : 06/04/2022  
 WIP No. . . : 20069  
 Veh.In/Out:  
 \*Tel.No. . . : Mobile: 98472080  
 Reg.No. . . : SMX3417G  
 Reg.date . . : 16/01/2020  
 Mileage .. : 0  
 Chassis No: VF1RFA00963212476

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	AIR INTAKE HOSE, BUM	1.0 EA	139.40			139.40	S
	AIR INTAKE GUIDE FRT	1.0 EA	165.30			165.30	S
	AIR FLAP GUIDE LOWER	1.0 EA	251.60			251.60	S
	BUMPER FRT TOP GRILL	1.0 EA	473.80			473.80	S
	GRILLA LINING PANEL	1.0 EA	346.80			346.80	S
	GRILLA TOP CHROMA ST	1.0 EA	231.60			231.60	S
	MLDG-GRILLE RAD, S4	1.0 EA	317.80			317.80	S
	LOGO FRT GRILLE GS4	1.0 EA	167.00			167.00	S
	STICKER M4S	1.0 EA	17.50			17.50	S
	LABEL TOP PANEL M4H	1.0 EA	8.80			8.80	S
	LABEL-DIESEL EXH EMI	1.0 EA	8.80			8.80	S
	WHEEL ARCH - FRT LH	1.0 EA	294.60			294.60	S
	WHEEL ARCH - FRT RH	1.0 EA	294.60			294.60	S
	WHEEL ARCH CLIP J5AL	20.0 EA	6.00			120.00	S
	BONNET FRT GS4	1.0 EA	1348.00		1	1,348.00	S
	BONNET INSULATE GS4	1.0 EA	315.70			315.70	S
	BONNET HINGE LH GS4	1.0 EA	134.30			134.30	S

### SERVICE ESTIMATE

##### - C00001      SL: SERVICE SALES - PC

Mr Nick Lim  
 #02-04 Lorong H Telok Kurau  
 The Bale

Singapore 425991

Closed by .... : Juan Paulo Bongon Ba  
 Svc Consultant :  
 Remarks ..... : Mr Nick Lim

GST Reg.No:M28920628X

Inv.No. . . : B&P                      0    Page 4  
 Inv.date. . : 06/04/2022  
 WIP No. . . : 20069  
 Veh.In/Out:  
 \*Tel.No. . . : Mobile: 98472080  
 Reg.No. . . : SMX3417G  
 Reg.date . . : 16/01/2020  
 Mileage .. : 0  
 Chassis No: VF1RFA00963212476

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BONNET HINGE RH GS4	1.0 EA	134.30			134.30	S
	BONNET DAMPER L&R GS	2.0 EA	120.20			240.40	S
	BONNET LOCK GS4	1.0 EA	191.10			191.10	S
	BUMPER FRT REINFORCE	1.0 EA	744.40			744.40	S
	LOWER RADIATOR PANEL	1.0 EA	569.50			569.50	S
	GRILLA PANEL INNER A	1.0 EA	1214.30			1,214.30	S
	GRILLA PANEL INNER L	1.0 EA	92.10			92.10	S
	GRILLA PANEL INNER L	1.0 EA	93.10			93.10	S
	COOLANT 5 LTR	2.0 EA	24.20			48.40	S
	GRILLA PANEL INNER T	2.0 EA	116.20			232.40	S
	BRACKET, FENDER FRT	1.0 EA	247.30			247.30	S
	BRACKET, FENDER FRT	1.0 EA	261.20			261.20	S
	FENDER BRACKET FRT L	1.0 EA	130.00			130.00	S
	BRACKET, FENDER FRT	1.0 EA	130.00			130.00	S
	RADIATOR AIR GUIDE F	1.0 EA	112.00			112.00	S
	AIR COOLER GUIDE AIR	1.0 EA	46.60			46.60	S
	FAN MOTOR GS4M4RS	1.0 EA	937.20			937.20	S

### SERVICE ESTIMATE

##### - C00001      SL: SERVICE SALES - PC

Mr Nick Lim  
 #02-04 Lorong H Telok Kurau  
 The Bale

Singapore 425991

Closed by .... : Juan Paulo Bongon Ba  
 Svc Consultant :  
 Remarks ..... : Mr Nick Lim

GST Reg.No:M28920628X

Inv.No. . . : B&P                      0    Page 5  
 Inv.date. . : 06/04/2022  
 WIP No. . . : 20069  
 Veh.In/Out:  
 \*Tel.No. . . : Mobile: 98472080  
 Reg.No. . . : SMX3417G  
 Reg.date . . : 16/01/2020  
 Mileage .. : 0  
 Chassis No: VF1RFA00963212476

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	AIR INTAKE FLAP GUID	1.0 EA	597.40			597.40	S
	A/C CONDENSER GS4 M4	1.0 EA	930.00			930.00	S
	RADIATOR S4 M4S GS4	1.0 EA	725.40			725.40	S
	AIR COOLER ASSY- GS4	1.0 EA	898.10			898.10	S
	HEADLAMP RH (Privile	1.0 EA	1877.70			1,877.70	S
	HEADLAMP LH (Privile	1.0 EA	1877.70			1,877.70	S
	FOG LAMP-RH FRT CAP	1.0 EA	248.10			248.10	S
	FOG LAMP-LH FRT CAP	1.0 EA	248.10			248.10	S
	BUMPER HARNESS- FRT	1.0 EA	198.40			198.40	S
	PARK SENSOR BOTH CTR	4.0 EA	557.20			2,228.80	S
	BLIND SPOT SENSOR GS	2.0 EA	361.70			723.40	S
	DASHBOARD	1.0 EA	3674.90			3,674.90	S
	DASHBOARD COVER GS4	1.0 EA	1025.70			1,025.70	S
	*E* PASSENGER AIR BA	1.0 EA	1211.00			1,211.00	S
	*E* SEAT BELT FRT LH	1.0 EA	743.40			743.40	S
	*E* SEAT BELT FRT RH	1.0 EA	743.40			743.40	S
	*E* SEAT BELT TENSIO	1.0 EA	210.90			210.90	S

### SERVICE ESTIMATE

##### - C00001      SL: SERVICE SALES - PC

Mr Nick Lim  
 #02-04 Lorong H Telok Kurau  
 The Bale

Singapore 425991

Closed by .... : Juan Paulo Bongon Ba  
 Svc Consultant :  
 Remarks ..... : Mr Nick Lim

GST Reg.No:M28920628X

Inv.No. . . : B&P                    0    Page 6  
 Inv.date. . : 06/04/2022  
 WIP No. . . : 20069  
 Veh.In/Out:  
 \*Tel.No. . . : Mobile: 98472080  
 Reg.No. . . : SMX3417G  
 Reg.date . . : 16/01/2020  
 Mileage .. :                    0  
 Chassis No: VF1RFA00963212476

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	*E* SEAT BELT TENSIO	1.0 EA	210.90			210.90	S
	SEAT BELT BUCKLE FRT	1.0 EA	263.50			263.50	S
	SEAT BELT BUCKLE FRT	1.0 EA	263.50			263.50	S
	*E* BELT-2ND ROW RH	1.0 EA	743.40			743.40	S
	BELT-2ND ROW LH	1.0 EA	963.30			963.30	S
	BELT-2ND ROW CTR	1.0 EA	963.30			963.30	S
	AIRBAG COMPUTER GS4	1.0 EA	1356.90			1,356.90	S
	*E* STEERING WHEEL A	1.0 EA	1148.80			1,148.80	S
	ROTARY SWITCH GS4 KJ	1.0 EA	429.90			429.90	S

Gross Total.                    56,369.70

**Labour Total            16,560.00**  
**Parts Total             39,809.70**  
**Package Total            0.00**

Net.....                    56,369.70  
 GST @ 7.0%                3,945.88  
 Total.....                 60,315.60  
 Paid.....                    0.00  
 Please Pay..                60,315.60

GST: S=StdRated; O=OutOfScope; Z=ZeroRated