



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 8T

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|---------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | HUB CAP WITH BLUE RING (BMW) (SN) | NECESSARY | 37.30 | 37.30 |
| 1 | ALLOY RIM 8JX20 STY SPK 890M (SN) | CUT | 1,568.95 | 1,568.95 |
| 1 | FRT RH DOOR (SN) | DENTED | 1,545.85 | 1,545.85 |
| 1 | PROTECTIVE STRIP PRIMED RHF (SN) | NECESSARY | 151.95 | 151.95 |
| 1 | FRT RH SIDE PANEL FINISHER (M)(SN) | CUT | 83.25 | 83.25 |
| 1 | M PERFORMANCE SIDE DECALS IN FROZEN (SN) | NECESSARY | 296.50 | 296.50 |
| 1 | EMBLEM (M)(SN) | NECESSARY | 83.80 | 83.80 |
| 1 | (S/L) DOOR WEATHERSTRIP (SN) | NECESSARY | 167.50 | 167.50 |
| 1 | FRT RH WHEEL ARCH TRIM PRIME (SN) | CUT | 318.75 | 318.75 |
| 18 | EXPANDING RIVET BLACK (SN) | NOT NECESSARY | 25.20 | - |
| 1 | SUNDRIES (SN) | NECESSARY | 150.00 | 150.00 |
| 5 | EXPANDING NUT (ADDITIONAL)(SN) | NECESSARY | 10.25 | 10.25 |
| | | | 4,439.30 | 4,414.10 |
| | <u>LABOUR</u> | | | |
| | TO REPLACE RIGHT FRONT DOOR,RIGHT FRONT WHEEL ARCH COVER AND TO MAKE GOOR RIGHT FRONT FENDER. | | 2,550.00 | 1,700.00 |
| | TO RESPRAY RIGHT FRONT DOOR,RIGHT FRONT FENDER AND RIGHT FRONT WHEEL ARCH COVER. | | 2,666.00 | 2,538.00 |
| | TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL). | | 118.00 | 112.00 |
| | TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS (1X). | | 531.00 | 505.00 |
| | TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING (1X). | | 94.00 | 89.00 |
| | TO CONDUCT CHECK ON ALL DOORS AND BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION. | | 177.00 | 168.00 |
| | TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING INCLUDING RESET AND CHECK AIR BAG FOR PROPER FUNCTION. | | 295.00 | 280.00 |
| | TO INSTALL "M" PERFORMANCE DECAL. | | 450.00 | 428.00 |
| | | | 6,881.00 | 5,820.00 |
| | GRAND TOTAL | | 11,320.30 | 10,234.10 |

Report Ref No. CS/SMR22003230/Evy3n2



| | | | |
|-----------------------------|--|--|-----------|
| RECOMMENDED COST OF REPAIRS | | | 10,234.10 |
|-----------------------------|--|--|-----------|

Report Ref No. CS/SMR22003230/Evy3n2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.