

T? AXA.
Itai Pony.

SMQ5032G.

Toyota Noah Hybrid 1797 cc

ZWR800382341

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: 30(SN) ✓

- | | | |
|---------------------------------|---------------|------------------------------|
| Front Number Plate. | | 30(SN) ✓ |
| Front Number Plate Holder. | }
ncp
m | 30(SN) ✓ |
| Front Bumper | Distorted | 1288.70 ✓ 1025 |
| Front Bumper Clips. | ncp | 30(SN) ✓ 75.30 |
| Front Bumper Side Holder x 02. | RH
2nd | 75.3 x 2 = 150.60 |
| Front Bumper Sponge. | could | 156.90 ✓ |
| Front Bumper Reinforcement | Perforated | 371.30 ✓ |
| Front Bumper Side Grille RH. | Delhd | 131.10 ✓ |
| Front Bumper Undercover | Delhd | 345.90 ✓ |
| Front Bumper Undercovers Clips. | ncp | 30(SN) ✓ |
| Front Bumper Sensor | Perf | 280(SN) ✓ |
| Front Bumper Lower Grille. | Delhd | 225.10 ✓ |
| Front Grille Upper | could | 571.70 ✓ |
| Front Grille Upper Clips | ncp | 20(SN) ✓ |

SMQ5032G

Front Grille Lower.	amb ^d	561.80	✓
Front Grille Lower Clips.	MR	20(SN)	✓
Front Grille Logo.	MR	75.90.	✓
Headlamp x 02.	Assembled	3181x2 = 6362	✓
Bonnet	Dented	1055.30.	✓
Bonnet Lock.	MR MR	188.90	X
Bonnet Hinge x 02.	Best	85.1x2 = 170.20.	✓
Front Brace Panel.	Best	122.10.	✓
Front Support Panel.	Buckled	945.10.	✓
Oil Cooler.	Dented	684.10.	✓
Air Con Condenser.	Best	1233.10.	58.80.
Air Con Condenser Side Guide x 02.	RH behind	58.9x2 = 117.80.	✓
Air Con Condenser Side Guide Clips.	MR 20(SN)		✓
Air Con Discharge Pipe.	HP	439.40	X
Air Con Suction Pipe.	MR	407.40	X.
Air Con Liquid Pipe.	Best	294.60	✓
Air Con Fan Motor	HP MR	504.90.	X

SMQ 5032 G.

Air Con Fan Blade.	new	164.90	+
Radiator	dryd	1552.30	/
Radiator Top Panel.	Rejs	441.50	+
Radiator Fan Cowling.	auhd	360.80	/
Radiator Fan Blade	new	164.90	+
Radiator Fan Motor.	new	510.40	+
Radiator Top Hose.	new	65.40	+
Radiator Coolant.	new	50(SN)	/
Radiator Top Mounting x 02.	new	$35.1 \times 2 = 70.20$	/
Horn.	xl new	82.30	+
Wiper Washer Tank.	Dehd	221.10	/
Wiper Washer Tank Motor	new	98.90	+
Wiper Washer Tank Neck.	Dehd	65.20	/
Wiper Panel Garnish.	2	488.20	+
Wiper Panel Garnish Clips.	2 new	30(SN)	+
Front RH Fender	Distorted	911.20	/
Front RH Fender Emblem.	new	102.50	/
Front RH Fender Glass	shattered	595.80	/
Front RH Fender Glass	new Sealant.	40(SN)	/

SMA S032 G.

- Front RH Fender Bracket. Best 59.60 ✓
- Front RH Fender Inner Shield. Com 232.90 ✓
- Front RH Fender Inner Shield caps. NU 30(SN) ✓
- Front RH Fender Inner Panel. Rep's 699.30 X
- Front RH Door. Rep's 1672.30 X
- Front RH Door Black Tape. NU 60(SN) X NN
- Front RH Door Weatherstripe. Rep 289.90 X
- Front RH Wheel Rim. Ut 800(SN) 500(SN)
- Front RH Tyre. New 280(SN) X
- Front RH Lower Arm. Best 579.80 ✓
- Front RH Knuckle Arm. 2nd 565.70 ✓
- Front RH Wheel Hub c/w Bearings. 2nd 330.90 ✓
- Front RH Shock Absorber. Best 449.20 ✓
- Front RH Anti-Roll Bar Linkage. Rep 173.70 X
- Front RH Tie Rod. New 135.90 X
- Sleeving Rack and Pinion. Rep 2901.50 X
- Engine Mounting (Front). Rep 289.30 X

20562.60

km 25%: 15421.57

S.N: 940

JMQ 50326.

Panel Beating	1800 1400
Spray Painting.	1600 1200
Wiring.	100 30
To spray buff coat.	150 80
To remove condenser and ? to top up air con gas ↓.	120 60
To remove radiator and ? to top up coolant ↓.	120 60
To transfer door fittings.	150 X
To replace engine mounting	200 X
To dismantle front undercarriage.	350 220
To remove steering rack and pinion.	180 X
To perform wheel alignment.	150 80.
Towing charges.	60. ✓
	3190
	total: 19551.95
	4/5: 15.6K.
	11 Days.