

ACCIDENT REPAIR ESTIMATES

Our Ref: TP / QX1589J

Type of Claim : OD

Vehicle No. : QX1589J

Make & Model : MERCEDES SPRINTER

Year of Manufacture : 2018

Chassis No. : WDB9066332P641425

Suggested Days of Repair : 5

Case Owner : LENTOR AMBULANCE

Date of Accident : 11/3/2022

Repair Estimates

Parts (a) Cost / List Price Items \$ 8,208.00

Plus/Less- 10.0% \$ 820.80

Total of Cost / List \$ 9,028.80

Labour \$ 800.00

Total Repair Cost \$ 9,828.80

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor

: Thavan

Company

: Lkh

Survey conducted on

: 8/4/22 at 1800

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 4 day(s)

(c) Resurvey : Required / Not Required



Vehicle No. : QX1589J
Make & Model : MERCEDES SPRINTER
Chassis No. : WDB9066332P641425

Case Owner	:	<u>LENTOR</u>
Year of Manufacture	:	<u>2018</u>
Type of Claim	:	<u>OD</u>

S/No	Labour Description	Estimated Price	Adjusted Price
1	Remove & replace front bumper	\$180.00	/
2	Remove & replace front grille , apron panel & number plate	\$180.00	100
3	Remove & replace Headlamp & wiring	\$80.00	30
4	Replace & Spray paint Engine Hood	\$180.00	/
5	Detailling for Engine Hood Stickers & Decals	\$180.00	Handwritten signature
	TOTAL	\$800.00	

Parts Estimate

S/No	Part Description	QTY	Cost Price
1	Front Bumper Assembly	1	\$1,320.00 ✓
2	Front Grille Panel	1	\$1,125.00 ✓
3	Front Grille Apron	1	\$255.00 ✓
4	Head Lamp Support Bracket	1	\$560.00 ✓
5	Head Lamp RH Assembly	1	\$1,854.00 ✓
6	Head Lamp LH Assembly	1	\$1,854.00 ✓
7	Front Engine Hood	1	\$840.00 ✓
8	Sticker & Decal for Engine Hood	1	\$400.00 ✓
	TOTAL:	8	\$8,208.00

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.