

(08/11/23)

ASS. REC. BY: Thavan

REF: CS/CTI 22003234/uvy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

X	
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: QX15895 Yr Regn: 14/3/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Ambulance

Make: Mercedes benz Sprinter c.c 2295

Colour: white A/C: Insured / Std / NI / NA

Sp.Reading: Not avail T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDB9066332P64425

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 235/65R16

R: 235/65R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 21/3/22 D.O.I. 8/4/22 / 800

Survey held at Inden / inden

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

____ S + RS. ____ SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Government
Owner ID:	035G
Vehicle Details	
Vehicle No.:	QX1589J
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Apr 2022
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	SPRINTER 316CDI/3665
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	65195534794285
Chassis No.:	WDB9066332P641425
Maximum Power Output:	-
Open Market Value:	\$190,214.00
Original Registration Date:	14 Mar 2019
First Registration Date:	14 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Mar 2029
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 11 Apr 2022

OK

ACCIDENT REPAIR ESTIMATES

Our Ref: TP / QX1589J

Type of Claim : OD

Vehicle No. : QX1589J

Make & Model : MERCEDES SPRINTER

Year of Manufacture : 2018

Chassis No. : WDB9066332P641425

Suggested Days of Repair : 5

Case Owner : LENTOR AMBULANCE

Date of Accident : 11/3/2022

Repair Estimates

Parts (a) Cost / List Price Items	\$ 8,208.00
Plus/Less 10.0%	\$ 820.80
Total of Cost / List	\$ 9,028.80

Labour \$ 800.00

Total Repair Cost \$ 9,828.80

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Thwan

Company : Lhh

Survey conducted on : 8/4/22 at 1800

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 4 day(s)

(c) Resurvey : Required / Not Required



Vehicle No. : QX1589J
Make & Model : MERCEDES SPRINTER
Chassis No. : WDB9066332P641425

Case Owner	:	<u>LENTOR</u>
Year of Manufacture	:	<u>2018</u>
Type of Claim	:	<u>OD</u>

S/No	Labour Description	Estimated Price	Adjusted Price
1	Remove & replace front bumper	\$180.00	/
2	Remove & replace front grille , apron panel & number plate	\$180.00	100
3	Remove & replace Headlamp & wiring	\$80.00	30
4	Replace & Spray paint Engine Hood	\$180.00	/
5	Detailing for Engine Hood Stickers & Decals	\$180.00	Am 875K
	TOTAL	\$800.00	

Parts Estimate

S/No	Part Description	QTY	Cost Price
1	Front Bumper Assembly	1	\$1,320.00 ✓
2	Front Grille Panel	1	\$1,125.00 ✓
3	Front Grille Apron	1	\$255.00 ✓
4	Head Lamp Support Bracket	1	\$560.00 ✓
5	Head Lamp RH Assembly	1	\$1,854.00 ✓
6	Head Lamp LH Assembly	1	\$1,854.00 ✓
7	Front Engine Hood	1	\$840.00 ✓
8	Sticker & Decal for Engine Hood	1	\$400.00 ✓
TOTAL		\$8,208.00	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.