

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 05/04/2022
TP Veh Reg No: SGU2115X

Estimate No: EST2200098

Date: 06 Apr 2022

Veh Reg No: **SKS3910Z**

Make/Model: TOYOTA
VIOSJGRADEMT

Chasis No: MHFBT9F3606030417

Reg. Date: 13/04/2015

Your Ref No: SGU2115X

Estimate Repair Cost to Vehicle No :SKS3910Z

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
List Price			
1	1 PC REAR BUMPER	452.80	
2	1 PC REAR BUMPER REINFORCEMENT	316.60	
3	1 PC REAR BUMPER SIDE RETAINER RH	113.90	
4	1 PC REAR BUMPER RETAINER (SMALL) LH	31.20	
5	1 PC REAR BUMPER MUDFLAP RH	56.90	
6	1 PC REAR BUMPER REFLECTOR - RH	179.80	
7	1 PC REAR PANEL	620.20	
8	1 PC REAR PANEL TRIM	232.20	
9	1 PC TAIL LAMP - RH	397.50	
10	1 PC REAR FENDER INNER TRIM RH	355.90	
11	1 PC BOOT LID RUBBER	166.40	
		2,923.40	
	Less 25%	730.85	2,192.57
Special Net			
12	1 SET REAR BUMPER STICKER	280.00	
13	1 SET REAR BUMPER MUDFLAP CLIPS RH	30.00	
14	1 SET REAR BUMPER CLIPS	40.00	
15	2 PCS "L" PLATE BRACKET	80.00	
16	1 SET REAR PANEL TRIM CLIPS	40.00	
17	1 SET REAR FENDER INNER TRIM CLIPS	60.00	
18	1 PC REAR FENDER STICKER RH	290.00	
		820.00	820.00
Labour			
19	1 TO CHECK WIRING	50.00	
20	1 TO REPLACE STICKERS	80.00	
21	1 TO REMOVE AND REFIT REAR INNER TRIM	80.00	
22	1 TO SPRAY UNDERSEAL	80.00	
23	1 (REAR) TO SPRAY PAINTING	900.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 05/04/2022
TP Veh Reg No: SGU2115X

Estimate No: EST2200098

Date: 06 Apr 2022

Veh Reg No: **SKS3910Z**

Make/Model: TOYOTA
VIOSJGRADEMT

Chasis No: MHFBT9F3606030417

Reg. Date: 13/04/2015

Your Ref No: SGU2115X

Estimate Repair Cost to Vehicle No :SKS3910Z

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
24	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	900.00	
		2.090.00	2.090.00
		Total	S\$ 5,102.57
		Add GST @ 7%	357.18
		Total Amount Payable	<u>S\$ 5,459.75</u>

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND FOUR HUNDRED FIFTY NINE AND CENTS
SEVENTY FIVE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time
which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE